



DRILLING & FISHING TOOLS AND BHA INSPECTION REPORT

Aberdeen Technical Services
www.aberdeents-iq.com
 Iraq –Basra – AlBarjisia
 Tel: +964 7833334444 +964 7822222633
 Emails:
akader@aberdeents.com
inspection@aberdeents-iq.com

CUSTOMER:	KERUI OILFIELD SERVICE DMCC	RIG NO.:	--	DEPARTMENT:	Fishing	PAGE NO.:	Page 2 of 2	REPORT NO.:	ATS-KRU-24-11-4224-001
LOCATION:	ATS / AlJuhud Workshop	REF NO.:	--	PO/FIRE NO.:	KRPO2024-46	JOB NO.:	ATS-KRU-24-11-4224	DATE:	13/11/2024



TOP SUB
DAMAGED SEAL



TOP SUB
DAMAGE THREAD



WASHPIPE
MISSING CHROME & ID CORRODED



BOTTOM SUB
ID CORRODED



FULL BODY PICTURE

COMMENTS:	THE ABOVE-MENTIONED ITEM WAS INSPECTED (FULL BODY) AND FOUND "REJECTED" AT THE TIME OF INSPECTION. * TOP SUB: DAMAGED SEAL * WASHPIPE: MISSING CHROME + ID CORRODED * BOTTOM SUB: ID CORRODED		NAME OF INSPECTOR:	TAYYAB ABBASI	SIGNATURE: 	Reviewed by:	Hasan Omran	STAMP & SIGNATURE:
	QUALIFICATION:	ASNT NDT LEVEL-II	QUALIFICATION:	ASNT NDT LEVEL-II		Inspection Supervisor		



ATS-BHA-F-24-001

