



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with client details: Client Name (HILONG OIL SERVICE AND ENG CO, Iraq), Location of Examination (HL 99 - RU193), Certificate Number (ATS-04-24-3135-019), Job Number (ATS-04-24-3135), Date of Examination (22-04-2024), Date of Certificate (22-04-2024), Last Examination Date (-), Next Date of Examination (After Repair)

Table with equipment details: Serial No. / Asset No. (A10), Description of The Equipment (BOW SHACKLE With HEX. Bolt, Nut, And Safety Cotter Pin: SIZE: 5/8" GRADE: 6 Manufactured: J & L F.O.S: 6:1), Qty: (1), SWL (3 1/4 Ton). Includes technical diagrams of the shackle.

Reference Standards: BS EN 13889:2003 + A1:2008

Table with examination questions: 'Is this the first examination after installation...', 'Was the examination carried out?', 'In accordance with an examination scheme?', 'After the occurrence of exceptional circumstances?'

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: Missing nut

Table with defect assessment: 'Is the above a defect which is of immediate danger to persons' (YES checked)

Table with defect assessment: 'Is the above a defect which is not yet but could become a danger to persons' (YES by)

Particulars of any repair, renewal or alteration required to remedy the defect identified above: Provide a certified Nut from the same original manufacturer

Particulars of any tests carried out as part of the examination: visual inspection: Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Table with fit for purpose: 'Is this Equipment Fit for Purpose?' (YES checked)

Table with signatures: Inspector Name (Hasan Omran, ASNT LEVEL II, LEEA Registered Technician), Authenticated By (Majd Dayoub), Stamp and Date (Aberdeen Technical Services stamp)

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Non-satisfactory at the time of Inspection and considered Unsafe for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021