



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

| | | | |
|---------------------------------|--------------------------------------------|----------------------------------|------------|
| Client Name: | HILONG OIL SERVICE AND ENG CO, Iraq | Date of Examination: | 22-04-2024 |
| Location of Examination: | HL 99 – RU193 | Date of Certificate: | 22-04-2024 |
| Certificate Number: | ATS-04-24-3135-022 | Last Examination Date: | - |
| Job Number: | ATS-04-24-3135 | Next Date of Examination: | N/A |

| Serial No: / Asset No: | Description of The Equipment | Qty: | SWL |
|----------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|-------|
| 00160 00276 00208 00308 | FLAT WOVEN WEBBING SLING Material: 100% polyester Date: 2018 Width: 1” Length: 1m Manufacturer: fa liang sling CO F.O.S: 5:1 Colour: Violet No. of Plys: 2 | 4 | 1 Ton |

| | |
|----------------------------|-----------------------------|
| Reference Standards | BS EN 1492-1:2000 + A1:2008 |
|----------------------------|-----------------------------|

| | | | | | | | | | |
|-----------------------------------------------------------------------------------------|-----|---|----|---|----------------------------------------------------|-----|---|----|---|
| Is this the first examination after installation or assembly at a new site or location? | | | | | Was the examination carried out? | | | | |
| | YES | | NO | ✓ | Within an interval of 6 months? | YES | ✓ | NO | |
| If the answer to the above question is YES has the equipment been installed correctly? | | | | | Within an interval of 12 months? | YES | | NO | ✓ |
| | YES | ✓ | NO | | In accordance with an examination scheme? | YES | ✓ | NO | |
| | | | | | After the occurrence of exceptional circumstances? | YES | | NO | ✓ |

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **Whole the webbing slings having safety factor less than the minimum 7:1 in the standard**


| | | | | |
|---------------------------------------------------------------|-----|---|----|--|
| Is the above a defect which is of immediate danger to persons | YES | ✓ | NO | |
|---------------------------------------------------------------|-----|---|----|--|

| | | |
|-----------------------------------------------------------------------------|--------|--|
| Is the above a defect which is not yet but could become a danger to persons | YES by | |
|-----------------------------------------------------------------------------|--------|--|

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **withdraw from service**

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually at the time of inspection

| | | | | |
|------------------------------------|-----|--|----|---|
| Is this Equipment Fit for Purpose? | YES | | NO | ✓ |
|------------------------------------|-----|--|----|---|

| | | |
|----------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|
| Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician | Authenticated By: Majd Dayoub | Stamp and Date:  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|-----------------------------------------------------------------------------------------------------------------|

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Non-satisfactory** at the time of Inspection and considered **Unsafe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021