



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	Daqing Petroleum Administration Bureau Co. Ltd. / Iraq	Date of Examination:	20-11-2024
Location of Examination:	DQ – 42 / Block 9	Date of Certificate:	20-11-2024
Certificate Number:	ATS-11-24-4595-011	Next Date of Examination:	-
Job Number:	ATS-11-24-4595	Last Date of Examination:	-

Serial No: / Asset No:	Description of The Equipment:	Qty:	SWL:
D13.0440148 D13.0440155	<p align="center"><b><u>RETRACTABLE FALL ARRESTER</u></b></p> <p><b>Manufacture:</b> Froment <b>Model:</b> Protector 10 <b>Life line:</b> 5mm Dia. <b>Mfrd:</b> 02/2013 <b>Length:</b> 10 m</p>	02	<b>150 Kgs</b>

<b>Reference Standards</b>	BS EN 360:2002 / BS EN 363:2018
----------------------------	---------------------------------

Is This The First Examination After Installation or Assembly at a New Site or location?	Was The Examination Carried Out?			
	YES		NO	✓

Identification of any Part Found to Have a Defect Which is or Could Become a Danger to Persons and a Description of the Defect: **heavily corroded wire rope and losing elasticity.**

Is The Above a Defect Which is of Immediate Danger to Persons: YES ✓ NO

Is The Above a Defect Which is not yet But Could Become a Danger to Persons: YES by

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above: **Rejected**

Particulars of any Tests Carried out as Part of the Examination: Visual Inspection:  
**Items Mentioned-Above was Inspected Visually at The Time of Inspection**

Is this Equipment Fit for Purpose? YES NO ✓

<b>Inspector Name, Qualifications &amp; signature:</b> Aram Dlawar ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	<b>Authenticated By:</b> Hasan Omran	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Unsatisfactory** at the time of Inspection and considered **unsafe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021