



Certificate-SCBA Inspection



Breathing Apparatus Details.

Customer	DPAB Co.Ltd Iraq Branch Block-9	Certificate No.:	QC230730-029
MFG:	Delta Plus	Issue Date:	July 30, 2023
Model No.:	NA	Due Date:	July 29, 2024
Job Number:	QC/JN/23/00264	S/No.:	588031

Inspection Results:

Parts	Inspection Items	Inspected	Remarks
Face Mask	Visor , Head Strep, Connector, cover of exhalation Valve, inhalation valve, leak tight silicon rubber, Oronasal guard, Reticulated hood.	√	Pass
Demand Valve	Air supply Connector, Outer Shell, and Manual Switch off button, Manual force air supply button, Medium Pressure.	√	Pass
Pressure Reducer	Working pressure form high Compressed to (0.7:1.25) MPa.	√	Pass
Pressure Indicator	Taking random read and checking leak.	√	Pass
Alarming Device	Test the alarm form 6 MPa to 0.25 MPa.	√	Pass
Back Plate Assembly	Shoulder Strap, Back Plate Shoulder Strap fastener, Reducer Holder, Waist Belt, Cylinder Fastener.	√	Pass

Final Result:

- The inspected item/items is/are acceptable for use at the time it had been inspected.

- The equipment is/are in specification.
- This inspection was carried out in compliance with Sample Respiratory Protection Program as per (The Occupational Safety and Health Administration (OHSA)) 29CFR1910.134 Respiratory Protection Standard.
- This certificate may not be reproduced other than in full by photographic process.
- This certificate refers only to the particular item/items submitted for inspection.
- This certificate is valid only with signature and stamp.

Inspected By : Mahdi Haleem

