



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 99	Date of Examination:	16.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	16.12.2023
Certificate Number:	ATS-12-23-2486-SV-001	Last Examination Date:	-
Job Number:	ATS-12-23-2486	Next Date of Examination:	15-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
S01 S02 S08 CS1 S20119	Air Winch Sheaves Manufacturer: Sjetro Size: 5/8" Location: Under Crown Block	05	3 TON

Reference Standards	As per client request & API 8C
----------------------------	---

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Aram Dlawar ASNT VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:
---	--	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the 16-12-2023 and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations & Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021