




Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-001	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
S22/010 015 H11	<p align="center">BOW SHACKLE</p> <p align="center">With Hex. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/4" GRADE: 6 Manufactured: J & L F.O.S: 6:1 Location: Rig Mast,</p> 	03	12 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	✓	
				Within an interval of 6 months?
				Within an interval of 12 months?
If the answer to the above question is YES has the equipment been installed correctly?				In accordance with an examination scheme?
				After the occurrence of exceptional circumstances?

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None			
Is the above a defect which is of immediate danger to persons	YES	NO	
Is the above a defect which is not yet but could become a danger to persons	YES by		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None			
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.			
Is this Equipment Fit for Purpose?	YES	✓	NO

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIE-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-002	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL10	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/4" GRADE: 6 Manufactured: J & L F.O.S: 6:1 Location: Rig Mast,</p> 	01	12 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	✓	
				Within an interval of 6 months?
				Within an interval of 12 months?
If the answer to the above question is YES has the equipment been installed correctly?				In accordance with an examination scheme?
				After the occurrence of exceptional circumstances?

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None			
Is the above a defect which is of immediate danger to persons	YES	NO	
Is the above a defect which is not yet but could become a danger to persons	YES by		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None			
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.			

Is this Equipment Fit for Purpose?	YES	✓	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-T-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-003	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
B 8333	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1" GRADE: 6 Manufactured: BASH-P F.O.S: 6:1 Location: Rig Mast,</p> 	01	8 1/2 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
 Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose?	YES	√	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-004	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
F 15	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: Crosby F.O.S: 6:1 Location: Rig Mast,</p> 	01	8 1/2 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose?	YES	√	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIP-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-005	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B 2020	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: Toyolift F.O.S: 6:1 Location: Rig Mast,</p> 	01	8 1/2 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose?	YES	√	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date(s) of above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-006	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
C 26	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/8"</p> <p>GRADE: 6</p> <p>Manufactured: J & L</p> <p>F.O.S: 6:1</p> <p>Location: Rig Mast,</p> 	01	9 1/2 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
				Within an interval of 12 months? YES NO √
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO
				After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose?	YES	√	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023 
---	--	--

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-007	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
AT 209 AT 210 AT 196 A3448A AT 201 AT 202	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8"</p> <p>GRADE: 6</p> <p>Manufactured: Toyolift</p> <p>F.O.S: 6:1</p> <p>Location: Secondary Retashion,</p> 	06	3 1/4 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose?	YES	√	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 
---	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date, time, place and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-008	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
26 10 HL 78 AM 004 MA 86	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8"</p> <p>GRADE: 6</p> <p>Manufactured: J & L</p> <p>F.O.S: 6:1</p> <p>Location: Secondary Retention,</p> 	05	3 1/4 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None			
Is the above a defect which is of immediate danger to persons	YES		NO
Is the above a defect which is not yet but could become a danger to persons	YES by		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None			
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.			
Is this Equipment Fit for Purpose?	YES	√	NO

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date given above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-009	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B 4449	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4"</p> <p>GRADE: 6</p> <p>Manufactured: Toyolift</p> <p>F.O.S: 6:1</p> <p>Location: Secondary Retention,</p> 	01	4 3/4 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	✓	
				Within an interval of 6 months?
				Within an interval of 12 months?
If the answer to the above question is YES has the equipment been installed correctly?				In accordance with an examination scheme?
				After the occurrence of exceptional circumstances?

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None			
Is the above a defect which is of immediate danger to persons	YES	NO	
Is the above a defect which is not yet but could become a danger to persons	YES by		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None			
Particulars of any tests carried out as part of the examination:			
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.			
Is this Equipment Fit for Purpose?	YES	NO	✓

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date, how, above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIE-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-10	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
11 12 13 14 15 16 17 18 19	<p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8"</p> <p>GRADE: 6</p> <p>Manufactured: J & L</p> <p>F.O.S: 6:1</p> <p>Location: Secondary Retention,</p> 	09	3 1/4 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	Within an interval of 12 months? YES NO √			
	YES		NO	In accordance with an examination scheme? YES √ NO
				After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **√** **NO**

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
---	--	---



THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIE-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-11	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
58 581	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8" GRADE: 6 Manufactured: J & L F.O.S: 6:1 Location: Secondary Retention,</p> 	02	3 1/4 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	✓	
Is the answer to the above question is YES has the equipment been installed correctly?	YES	NO	✓	
	YES	NO		✓

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None			
Is the above a defect which is of immediate danger to persons	YES	NO	
Is the above a defect which is not yet but could become a danger to persons	YES by		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None			
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.			

Is this Equipment Fit for Purpose?	YES	✓	NO
Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:	
Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Hasan Omran	 11-12-2023	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIE-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with client details: Client Name (HILONG OIL SERVICE AND ENG CO, Iraq), Location (HILONG BASE RUMAILA), Certificate Number (ATS-12-23-2486-12), Job Number (ATS-12-23-2486), Date of Examination (05-Dec-2023), Date of Certificate (10-Dec-2023), Last Examination Date (Apr-2023), Next Date of Examination (04-June-2024)

Table with equipment details: Serial No./Asset No (651, 652, 653, 02), Description (BOW SHACKLE With HEX, Bolt, Nut, And Safety Cotter Pin), Qty (04), SWL (6 1/2 ton). Includes technical diagrams of the shackle.

Reference Standards: BS EN 13889:2003+A1:2008

Table with examination results: Was the examination carried out? (YES/NO), Within an interval of 6 months? (YES/NO), Within an interval of 12 months? (YES/NO), In accordance with an examination scheme? (YES/NO), After the occurrence of exceptional circumstances? (YES/NO)

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None

Is the above a defect which is of immediate danger to persons: YES/NO

Is the above a defect which is not yet but could become a danger to persons: YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: None

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES/NO

Table with inspector and authenticator details: Inspector Name (Syed Aamir Ali, ASNT LEVEL II, VT,MT,PT,UT, LEEA), Authenticated By (Hasan Omran), Stamp and Date (11-12-2023)

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-13	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
019	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: DY F.O.S: 6:1 Location: Mast Guy Line,</p> 	01	6 1/2 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES	NO	✓	
				Within an interval of 6 months?
				Within an interval of 12 months?
If the answer to the above question is YES has the equipment been installed correctly?				In accordance with an examination scheme?
				After the occurrence of exceptional circumstances?

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None			
Is the above a defect which is of immediate danger to persons	YES	NO	
Is the above a defect which is not yet but could become a danger to persons	YES by		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None			
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.			
Is this Equipment Fit for Purpose?	YES	NO	✓

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-14	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
DF 3	<p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: J & L F.O.S: 6:1 Location: Mast Guy Line,</p> 	01	6 1/2 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None							
Is the above a defect which is of immediate danger to persons			YES		NO		
Is the above a defect which is not yet but could become a danger to persons			YES by				
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None							
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.							
Is this Equipment Fit for Purpose?				YES	√	NO	

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 
---	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIP-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-15	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
CR 03 475	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4" GRADE: 6 Manufactured: J & L F.O.S: 6:1 Location: Mast,</p> 	02	4 3/4 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None						
Is the above a defect which is of immediate danger to persons			YES		NO	
Is the above a defect which is not yet but could become a danger to persons			YES by			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None						
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.						

Is this Equipment Fit for Purpose?				YES	√	NO	
Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran		Stamp and Date: 11-12-2023				



THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-16	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL 29	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: DSL F.O.S: 6:1 Location: Mast,</p> 	01	6 1/2 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
				Within an interval of 6 months?
				Within an interval of 12 months?
If the answer to the above question is YES has the equipment been installed correctly?				In accordance with an examination scheme?
				After the occurrence of exceptional circumstances?

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None			
Is the above a defect which is of immediate danger to persons			YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons			YES by <input type="checkbox"/>
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None			
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.			

Is this Equipment Fit for Purpose?			YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023	



THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LUT-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-17	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
F3 F4	<p align="center">DEE SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/2" GRADE: 6 Manufactured: J & L F.O.S: 6:1 Location: BOP,</p> 	02	17 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months? YES √ NO Within an interval of 12 months? YES NO √
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose?	YES	√	NO
Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIE-F-002 ISSUE 3- MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-18	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
654 655 656	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8” GRADE: 6 Manufactured: J & L F.O.S: 6:1 Location: Mast,</p> 	03	6 1/2 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None									
Is the above a defect which is of immediate danger to persons						YES		NO	
Is the above a defect which is not yet but could become a danger to persons						YES by			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None									
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.									

Is this Equipment Fit for Purpose?	YES	√	NO	
Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran		Stamp and Date: 11-12-2023	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date/time above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-19	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL 34	<p align="center">DEE SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: XN F.O.S: 6:1 Location: Mast,</p> 	01	6 1/2 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None									
Is the above a defect which is of immediate danger to persons						YES		NO	
Is the above a defect which is not yet but could become a danger to persons						YES by			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None									
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.									

Is this Equipment Fit for Purpose?	YES	√	NO	
Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran		Stamp and Date: 11-12-2023	



THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F 002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-20	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
02/20	<p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8" GRADE: 6 Manufactured: J & L F.O.S: 6:1 Location: Mast,</p> 	01	3 1/4 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months? YES √ NO Within an interval of 12 months? YES NO √
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √
	Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None				
Is the above a defect which is of immediate danger to persons				YES NO	
Is the above a defect which is not yet but could become a danger to persons				YES by	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None					
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.					

Is this Equipment Fit for Purpose?	YES	√	NO
Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran		Stamp and Date: 11-12-2023

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LEF-F-002 ISSUE 3- MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-21	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL99-001 HL99-002	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 2 1/2" GRADE: 6 Manufactured: J & L F.O.S: 6:1 Location: Mast,</p> 	02	55 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose?	YES	√	NO
Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran		Stamp and Date: 

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-E-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-22	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
951	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/8"</p> <p>GRADE: 6</p> <p>Manufactured: J & L</p> <p>F.O.S: 6:1</p> <p>Location: Mast,</p> 	01	9 1/2 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None									
Is the above a defect which is of immediate danger to persons						YES		NO	
Is the above a defect which is not yet but could become a danger to persons						YES by			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None									
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.									

Is this Equipment Fit for Purpose?	YES	√	NO	
Inspector Name, Qualifications & signature:	Authenticated By:		Stamp and Date:	
Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Hasan Omran			

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date mentioned above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-23	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
07 375 CR07	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8” GRADE: 6 Manufactured: J & L F.O.S: 6:1 Location: Mast,</p> 	03	3 1/4 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None									
Is the above a defect which is of immediate danger to persons						YES		NO	
Is the above a defect which is not yet but could become a danger to persons						YES by			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None									
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.									

Is this Equipment Fit for Purpose?	YES	√	NO	
Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran		Stamp and Date: 11-12-2023	



THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-24	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
50 51	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: J & L F.O.S: 6:1 Location: Mast,</p> 	02	6 1/2 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose?	YES	√	NO
Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LLF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-25	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
657 H22	<p align="center">BOW SHACKLE</p> <p align="center">With HEX. Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: DY F.O.S: 6:1 Location: Mast,</p> 	02	6 1/2 ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose?	YES	√	NO
Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:  11-12-2023	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIP-F-002 ISSUE 3 - MAR 2021