




Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	05-Dec-2023
<b>Location of Examination:</b>	HILONG BASE RUMAILA	<b>Date of Certificate:</b>	10-Dec-2023
<b>Certificate Number:</b>	ATS-12-23-2486-26	<b>Last Examination Date:</b>	Apr-2023
<b>Job Number:</b>	ATS-12-23-2486	<b>Next Date of Examination:</b>	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A 5067 B 202	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX. Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 7/8” <b>GRADE:</b> 6 <b>Manufactured:</b> Toyolift <b>F.O.S:</b> 6:1 <b>Location:</b> Mast,</p> 	02	6 1/2 ton
<b>Reference Standards</b>	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?	YES	√	NO	
					Within an interval of 6 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: <b>None</b>									
Is the above a defect which is of immediate danger to persons						YES		NO	
Is the above a defect which is not yet but could become a danger to persons						YES by			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: <b>None</b>									
Particulars of any tests carried out as part of the examination:  <b>Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.</b>									

Is this Equipment Fit for Purpose?	YES	√	NO	
<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Syed Aamir Ali:</b> <b>ASNT LEVEL II</b> <b>VT,MT,PT,UT</b> <b>LEEA</b>	<b>Authenticated By:</b>  <b>Hasan Omran</b>		<b>Stamp and Date:</b>  <b>11-12-2023</b>	



**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F 002 ISSUE 3 - MAR 2021






## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	05-Dec-2023
<b>Location of Examination:</b>	HILONG BASE RUMAILA	<b>Date of Certificate:</b>	10-Dec-2023
<b>Certificate Number:</b>	ATS-12-23-2486-27	<b>Last Examination Date:</b>	Apr-2023
<b>Job Number:</b>	ATS-12-23-2486	<b>Next Date of Examination:</b>	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
52	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX. Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 7/8" <b>GRADE:</b> 6 <b>Manufactured:</b> DSL <b>F.O.S:</b> 6:1 <b>Location:</b> Mast,</p> 	01	6 1/2 ton
<b>Reference Standards</b>	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: <b>None</b>									
Is the above a defect which is of immediate danger to persons						YES		NO	
Is the above a defect which is not yet but could become a danger to persons						YES by			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: <b>None</b>									
Particulars of any tests carried out as part of the examination:  <b>Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.</b>									

Is this Equipment Fit for Purpose?	YES	√	NO	
<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Syed Aamir Ali:</b> <b>ASNT LEVEL II</b> <b>VT,MT,PT,UT</b> <b>LEEA</b>	<b>Authenticated By:</b>  <b>Hasan Omran</b>		<b>Stamp and Date:</b>  <b>11-12-2023</b>	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	05-Dec-2023
<b>Location of Examination:</b>	HILONG BASE RUMAILA	<b>Date of Certificate:</b>	10-Dec-2023
<b>Certificate Number:</b>	ATS-12-23-2486-28	<b>Last Examination Date:</b>	Apr-2023
<b>Job Number:</b>	ATS-12-23-2486	<b>Next Date of Examination:</b>	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
098	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX. Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 7/8" <b>GRADE:</b> 6 <b>Manufactured:</b> Crosby <b>F.O.S:</b> 6:1 <b>Location:</b> Mast,</p> 	01	6 1/2 ton
<b>Reference Standards</b>	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: <b>None</b>									
Is the above a defect which is of immediate danger to persons						YES		NO	
Is the above a defect which is not yet but could become a danger to persons						YES by			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: <b>None</b>									
Particulars of any tests carried out as part of the examination:  <b>Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.</b>									

Is this Equipment Fit for Purpose?	YES	√	NO	
<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Syed Aamir Ali:</b> <b>ASNT LEVEL II</b> <b>VT,MT,PT,UT</b> <b>LEEA</b>	<b>Authenticated By:</b>  <b>Hasan Omran</b>		<b>Stamp and Date:</b>  <b>11-12-2023</b>	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3- MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	05-Dec-2023
<b>Location of Examination:</b>	HILONG BASE RUMAILA	<b>Date of Certificate:</b>	10-Dec-2023
<b>Certificate Number:</b>	ATS-12-23-2486-29	<b>Last Examination Date:</b>	Apr-2023
<b>Job Number:</b>	ATS-12-23-2486	<b>Next Date of Examination:</b>	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
11	<p align="center"><b>DEE SHACKLE</b></p> <p align="center"><b>With HEX. Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 7/8"  <b>GRADE:</b> 6  <b>Manufactured:</b> J &amp; L  <b>F.O.S:</b> 6:1  <b>Location:</b> Mast,</p> 	01	6 1/2 ton
<b>Reference Standards</b>	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
*Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.*

Is this Equipment Fit for Purpose?	YES	√	NO	
<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Syed Aamir Ali:</b> <b>ASNT LEVEL II</b> <b>VT,MT,PT,UT</b> <b>LEEA</b>	<b>Authenticated By:</b>  <b>Hasan Omran</b>		<b>Stamp and Date:</b>  <b>11-12-2023</b>	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	05-Dec-2023
<b>Location of Examination:</b>	HILONG BASE RUMAILA	<b>Date of Certificate:</b>	10-Dec-2023
<b>Certificate Number:</b>	ATS-12-23-2486-30	<b>Last Examination Date:</b>	Apr-2023
<b>Job Number:</b>	ATS-12-23-2486	<b>Next Date of Examination:</b>	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B 3918 B 3921 B 3922 B 3924	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX. Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1 1/8”</p> <p><b>GRADE:</b> 6</p> <p><b>Manufactured:</b> Toyolift</p> <p><b>F.O.S:</b> 6:1</p> <p><b>Location:</b> Sewage Tank,</p> 	04	9 1/2 ton
<b>Reference Standards</b>	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: <b>None</b>									
Is the above a defect which is of immediate danger to persons						YES		NO	
Is the above a defect which is not yet but could become a danger to persons						YES by			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: <b>None</b>									
Particulars of any tests carried out as part of the examination:  <b>Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.</b>									

Is this Equipment Fit for Purpose?	YES	√	NO	
<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Syed Aamir Ali:</b> <b>ASNT LEVEL II</b> <b>VT,MT,PT,UT</b> <b>LEEA</b>	<b>Authenticated By:</b>  <b>Hasan Omran</b>		<b>Stamp and Date:</b>  	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with 4 columns: Client Name, Location of Examination, Certificate Number, Job Number, Date of Examination, Date of Certificate, Last Examination Date, Next Date of Examination.

Table with 4 columns: Serial No. / Asset No., Description of The Equipment, Qty., SWL. Includes details for BOW SHACKLE and technical diagrams.

Reference Standards BS EN 13889:2003+A1:2008

Table with 2 main columns: Question (e.g., 'Is this the first examination...'), and a grid for 'Was the examination carried out?' with YES/NO/√ options.

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: None

Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES √ NO

Table with 3 columns: Inspector Name, Qualifications & signature; Authenticated By; Stamp and Date.

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



ATS-LIF-F-002 ISSUE 3- MAR 2021