



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-01	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
GY18121268 GY18121269 GY18114839	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC - Mechanically Spliced with Aluminium Ferrules Hard Eye At Both Ends, Dim: 16 mm (L) X 1.5 M Location: Secondary Retention, F.O.S: 5:1	03	27 KN

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:  11-12-2023
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with client details: Client Name (HILONG OIL SERVICE AND ENG CO, Iraq), Location (HILONG BASE RUMAILA), Certificate Number (ATS-12-23-2486-02), Job Number (ATS-12-23-2486), Date of Examination (05-Dec-2023), Date of Certificate (10-Dec-2023), Last Examination Date (Apr-2023), Next Date of Examination (04-June-2024)

Table with equipment details: Serial No / Asset No (LH 3), Description (SINGLE-LEG WIRE ROPE SLING, IWRC - Mechanically Spliced with Aluminium Ferrules, Hard Eye At Both Ends, Dim: 16 mm (L) X 1.2 M, Location: Secondary Retention, F.O.S: 5:1), Qty (01), SWL (3 ton)

Reference Standards: BS EN 13414-1:2003+A2:2008

Table with examination questions: Was the examination carried out? (6 months, 12 months), In accordance with an examination scheme?, After the occurrence of exceptional circumstances?

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None

Is the above a defect which is of immediate danger to persons: YES, NO

Is the above a defect which is not yet but could become a danger to persons: YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: None

Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose?: YES, NO

Table with inspector and authentication details: Inspector Name (Syed Aamir Ali, ASNT LEVEL II, VT,MT,PT,UT, LEEA), Authenticated By (Hasan Omran), Stamp and Date (11-12-2023)

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-03	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
61554	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye At Both Ends, Dim: 16 mm (L) X 1.5 M Location: Secondary Retention, F.O.S: 5:1</p>	01	3.3 ton

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?	YES	√	NO	
					Within an interval of 6 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	--------------------------------------



THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 / SUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-04	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B 1042 B 836	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye At Both Ends, Dim: 13 mm (L) X 2 M Location: Secondary Retention, F.O.S: 5:1	02	2.1 ton

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?	YES	√	NO	
					Within an interval of 6 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Aberdeen Technical Services and General Transportation



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-05	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
GS1901690 GS1901691	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye X Open Spelter Socket, Dim: 16 mm (L) X 23.3 M Location: Store, F.O.S: 5:1	02	135 KN

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?				√	Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	---



THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation
Iraq - Basra - AlBarjisia
Akader@aberdeents.com / inspection@aberdeents-iq.com
Tel: +964 782222633 / +9647827451212



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with client details: Client Name (HILONG OIL SERVICE AND ENG CO, Iraq), Location (HILONG BASE RUMAILA), Certificate Number (ATS-12-23-2486-06), Job Number (ATS-12-23-2486), Date of Examination (05-Dec-2023), Date of Certificate (10-Dec-2023), Last Examination Date (Apr-2023), Next Date of Examination (04-June-2024)

Table with equipment details: Serial No / Asset No (GY18114835, GY18114836), Description (SINGLE-LEG WIRE ROPE SLING, IWRC Mechanically Spliced with Aluminium Ferrules, Hard Eye at Both End's, Dim: 19 mm (L) X 22.13 M, Location: Store, F.O.S: 5:1), Qty (02), MBL (45.8 KN)

Reference Standards: BS EN 13414-1:2003+A2:2008

Inspection questions table: Was the examination carried out? Within an interval of 6 months? Within an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons: YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: None

Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Syed Aamir Ali, ASNT LEVEL II, VT,MT,PT,UT, LEEA. Authenticated By: Hasan Omran. Stamp and Date: 11-12-2023

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

ATS-LIF-F 002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-07	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
GY18121267	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye at Both End's, Dim: 19 mm (L) X 6.4 M Location: Store, F.O.S: 5:1</p>	01	45.8 KN

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	---



THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the dates shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-08	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
GY18121266	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye at Both End's, Dim: 19 mm (L) X 5.75 M Location: Store, F.O.S: 5:1</p>	01	45.8 KN

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-09	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
GS1901695 GS1901696	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Open Spelter Socket X Plane End, Dim: 11 mm (L) X 66 M Location: Store, F.O.S: 5:1</p>	02	71.1 KN

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
---	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting

ATS-LTF-F-002 REV 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-010	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
GY18114833	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye at Both Ends, Dim: 10 mm (L) X 36.5 M Location: Store, F.O.S: 5:1</p>	01	10.6 KN

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-011	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	09-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
GY18114834 GY18121262 GY18121263	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye at Both Ends, Dim: 10 mm (L) X 36.5 M Location: Store, F.O.S: 5:1	03	10.6 KN

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LE-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-012	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
GY18121303 GY18121307 GY18121285 GY18121288 GY18121280 GY18121292 GY18121302 GY18121295 GY18121309 GY18121290	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye at Both Ends, Dim: 10 mm (L) X 13.5 M Location: Store, F.O.S: 5:1	10	10.6 KN

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:
--	--	--------------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-013	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
GY18121289 GY18121294 GY18121305 GY18121300 GY18121296 GY18121306 GY18121304 GY18114876 GY18114879 GY18114875	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye at Both Ends, Dim: 10 mm (L) X 13.5 M Location: Store, F.O.S: 5:1	10	10.6 KN

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√	
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIE-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-014	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
GY18114851 GY18114861 GY18114855 GY18114850 GY18114858 GY18114854 GY18114849 GY18114870 GY18114856 GY18114869	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye at Both Ends, Dim: 10 mm (L) X 13.5 M Location: Store, F.O.S: 5:1	10	10.6 KN

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date/s shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIE-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-015	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
GY18114874 GY18114860 GY18121283 GY18121281 GY18121282 GY18121391 GY18121286 GY18121283 GY18121284 GY18121308 GY18121287 GY18121279	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye at Both Ends, Dim: 10 mm (L) X 13.5 M Location: Store, F.O.S: 5:1	10	10.6 KN

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023 
--	--	--

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operation Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-016	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
GY18114880	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye at Both Ends, Dim: 13 mm (L) X 60 M Location: Store, F.O.S: 5:1</p>	01	17.9 KN

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
---	--	---



THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-017	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
GS1901688 GS1901699	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center"><u>GUY LINE</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye X Open Spelter Socket, Dim: 20 mm (L) X 38.2 M Location: Mast, F.O.S: 5:1</p>	02	211.5 KN
Reference Standards	BS EN 13414-1:2003+A2:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None									
Is the above a defect which is of immediate danger to persons						YES		NO	
Is the above a defect which is not yet but could become a danger to persons						YES by			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None									
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.									
Is this Equipment Fit for Purpose?						YES	√	NO	

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations- Lifting Equipment- Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-018	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
ATS1223-001 ATS1223-002	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center"><u>GUY LINE</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye X Open Spelter Socket, Dim: 16 mm (L) X 36 M Location: Mast, F.O.S: 5:1</p>	02	15 KN
Reference Standards	BS EN 13414-1:2003+A2:2008		

Is this the first examination after installation or assembly at a new site or location?	YES	NO	√	Was the examination carried out?				
				Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		Within an interval of 12 months?	YES		NO	√
				In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None			
Is the above a defect which is of immediate danger to persons	YES		NO
Is the above a defect which is not yet but could become a danger to persons	YES by		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None			
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.			
Is this Equipment Fit for Purpose?	YES	√	NO

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the dates mentioned above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIP-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-019	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
ATS1223-004 ATS1223-005	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center"><u>GUY LINE</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye at Both End's, Dim: 16 mm (L) X 38 M Location: Mast, F.O.S: 5:1</p>	02	15 KN
Reference Standards	BS EN 13414-1:2003+A2:2008		

Is this the first examination after installation or assembly at a new site or location?	YES	NO	√	Was the examination carried out?			
				Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		Within an interval of 12 months?	YES		NO
				In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None			
Is the above a defect which is of immediate danger to persons	YES		NO
Is the above a defect which is not yet but could become a danger to persons	YES by		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None			
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.			
Is this Equipment Fit for Purpose?	YES	√	NO

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	--



THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-020	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
ATS1223-003 ATS1223-006	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center"><u>GUY LINE</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye at Both End's, Dim: 16 mm (L) X 36 M Location: Mast, F.O.S: 5:1</p>	02	15 KN
Reference Standards	BS EN 13414-1:2003+A2:2008		

Is this the first examination after installation or assembly at a new site or location?	YES	NO	√	Was the examination carried out?				
				Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		Within an interval of 12 months?	YES		NO	√
				In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None			
Is the above a defect which is of immediate danger to persons	YES		NO
Is the above a defect which is not yet but could become a danger to persons	YES by		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None			
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.			
Is this Equipment Fit for Purpose?	YES	√	NO

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operation: Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-021	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
ATS1223-007 ATS1223-008	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center"><u>GUY LINE</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye at Both End's, Dim: 20 mm (L) X 21.5 M Location: Mast, F.O.S: 5:1</p>	02	20 KN
Reference Standards	BS EN 13414-1:2003+A2:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None							
Is the above a defect which is of immediate danger to persons			YES		NO		
Is the above a defect which is not yet but could become a danger to persons			YES by				
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None							
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.							
Is this Equipment Fit for Purpose?				YES	√	NO	

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
---	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-022	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
ATS1223-009 ATS1223-010	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center"><u>GUY LINE</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye at Both End's, Dim: 16 mm (L) X 20 M Location: Mast, F.O.S: 5:1</p>	02	15 KN
Reference Standards	BS EN 13414-1:2003+A2:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None									
Is the above a defect which is of immediate danger to persons						YES		NO	
Is the above a defect which is not yet but could become a danger to persons						YES by			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None									
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.									
Is this Equipment Fit for Purpose?						YES	√	NO	

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023 
--	--	--

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-023	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
ATS1223-011 ATS1223-012	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center"><u>GUY LINE</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye at Both End's, Dim: 16 mm (L) X 23 M Location: Mast, F.O.S: 5:1</p>	02	15 KN
Reference Standards	BS EN 13414-1:2003+A2:2008		

Is this the first examination after installation or assembly at a new site or location?	YES	NO	√	Was the examination carried out?				
				Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		Within an interval of 12 months?	YES		NO	√
				In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None			
Is the above a defect which is of immediate danger to persons	YES		NO
Is the above a defect which is not yet but could become a danger to persons	YES by		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None			
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.			
Is this Equipment Fit for Purpose?	YES	√	NO

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIE-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-024	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL:
GS1901692 GS1901693	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center"><u>GUY LINE</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye X Open Spelter Socket, Dim: 16 mm (L) X 20.25 M Location: Mast, F.O.S: 5:1</p>	02	135 KN
Reference Standards	BS EN 13414-1:2003+A2:2008		

Is this the first examination after installation or assembly at a new site or location?	YES	NO	√	Was the examination carried out?				
				Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		Within an interval of 12 months?	YES		NO	√
				In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None			
Is the above a defect which is of immediate danger to persons	YES		NO
Is the above a defect which is not yet but could become a danger to persons	YES by		
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None			
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.			
Is this Equipment Fit for Purpose?	YES	√	NO

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the dates shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with client details: Client Name (HILONG OIL SERVICE AND ENG CO, Iraq), Location (HILONG BASE RUMAILA), Certificate Number (ATS-12-23-2486-025), Job Number (ATS-12-23-2486), Date of Examination (05-Dec-2023), Date of Certificate (10-Dec-2023), Last Examination Date (Apr-2023), Next Date of Examination (04-June-2024)

Table with equipment details: Serial No / Asset No (GS1901694, GS1901695), Description (SINGLE-LEG WIRE ROPE SLING GUY LINE, IWRC Mechanically Spliced with Aluminium Ferrules, Hard Eye X Open Spelter Socket, Dim: 16 mm (L) X 20.45 M, Location: Mast, F.O.S: 5:1), Qty (02), MBL (135 KN), Reference Standards (BS EN 13414-1:2003+A2:2008)

Table with examination questions: Is this the first examination after installation... Was the examination carried out? (Within an interval of 6 months, 12 months), If the answer to the above question is YES has the equipment been installed correctly? (In accordance with an examination scheme, After the occurrence of exceptional circumstances?)

Table with defect identification: Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None. Is the above a defect which is of immediate danger to persons? Is the above a defect which is not yet but could become a danger to persons? Particulars of any repair, renewal or alteration required to remedy the defect identified above: None. Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Table with fit for purpose and signatures: Is this Equipment Fit for Purpose? (YES, NO), Inspector Name, Qualifications & signature (Syed Aamir Ali, ASNT LEVEL II, VT,MT,PT,UT, LEEA), Authenticated By (Hasan Omran), Stamp and Date (11-12-2023)

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021

