



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-026	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
B 3933	<p align="center"><u>4-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules C/W Master Link on Top Hard Eye At Both End Dim: 22 mm (L) X 6 M Location: Sewage Tank, F.O.S: 5:1</p>	01	13 ton

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√	
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 11-12-2023
---	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operation, Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIP-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-027	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
A 5242 A 5243	<p align="center"><u>TWO-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules</p> <p align="center">C/W Master Link on Top</p> <p align="center">Hard Eye At Both End</p> <p align="center">Dim: 16 mm (L) X 1.5 M</p> <p align="center">Location: Electric Panel,</p> <p align="center">F.O.S: 5:1</p>	02	4.6 ton

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√	
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons

YES		NO	
-----	--	----	--

Is the above a defect which is not yet but could become a danger to persons

YES by	
--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose?

YES	√	NO	
-----	---	----	--

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
<p align="center">Syed Aamir Ali:</p> <p align="center">ASNT LEVEL II</p> <p align="center">VT,MT,PT,UT</p> <p align="center">LEEA</p>	<p>Hasan Omran</p>	 <p>11-12-2023</p>

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operation - Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021

