



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Rig Number, Job Number, etc. Values include Hilong Oil Services & Engineering, HL99, and ATS-12-23-2486.

Table with 5 columns: Date of Examination, Date of Report, Certificate No. Values include 07/12/2023 and ATS-12-23-2486-MPI-020.

Main equipment details table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes photos of pad eyes.

Reference Standard and examination questions table. Reference: LEEA DOC 048:2015. Questions about examination frequency and safety.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

NDT Equipment Details table with columns: Standard, Viewing Condition, Colored Media, Method, WET. Lists equipment like Yoke, Vernier Caliper, etc.

NDT Results

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect: NONE

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

Inspector and authenticator information table. Name of Inspector: Jaafar Badr. Name of person authenticating this report: Hasan Omran. Latest date by which next thorough examination must be carried out: 06-06-2024.





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Rig Number, Job Number, etc. Values: Hilong Oil Services & Engineering, HL99, ATS-12-23-2486

Table with 5 columns: Date of Examination, Date of Report, Certificate No. Values: 07/12/2023, 07/12/2023, ATS-12-23-2486-MPI-021

Main equipment details table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes images of pad eyes.

Reference Standard and examination questions table. Reference: LEEA DOC 048:2015. Questions about examination frequency and safety.

Defect identification and safety table. Questions about defects and equipment safety. Includes 'IS THIS EQUIPMENT SAFE TO OPERATE?' section.

NDT Equipment Details table. Lists standards (API RP 4G, ASTM E709), viewing conditions, media, and due dates for various NDT equipment.

NDT Results section. States 'Visual and MPI carried out for the above description and found free of surface defects at the time of inspection'.

Inspector and authenticator table. Name of Inspector: Jaafar Badr. Name of person authenticating: Hasan Omran. Latest date by which next thorough examination must be carried out: 06-06-2024.





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with client details: Client Name: Hilong Oil Services & Engineering, Rig Number: HL99, Job Number: ATS-12-23-2486

Table with examination details: Date of Examination: 07/12/2023, Date of Report: 07/12/2023, Certificate No: ATS-12-23-2486-MPI-022

Main equipment table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes.

Reference Standard: LEEA DOC 048:2015. Inspection questions and results regarding examination frequency and safety.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with NDT Equipment Details including Standard, Yoke, Vernier Caliper, White Contrast, and Black Ink specifications.

NDT Results: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection. Identification of any part found to have a defect and a description of the defect: NONE

Inspector and authenticator details: Name of Inspector: Jaafar Badr, Name of person authenticating this report: Hasan Omran, Latest date by which next thorough examination must be carried out: 06-06-2024





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with client details: Client Name: Hilong Oil Services & Engineering, Rig Number: HL99, Job Number: ATS-12-23-2486

Table with examination details: Date of Examination: 07/12/2023, Date of Report: 07/12/2023, Certificate No: ATS-12-23-2486-MPI-023

Main equipment table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes with dimensions and photos.

Reference Standard: LEEA DOC 048:2015. Inspection questions regarding examination frequency and installation correctness.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with NDT Equipment Details including Standard, Yoke, Vernier Caliper, White Contrast, Black Ink, Viewing Condition, Colored Media, Method, and Due Date.

NDT Results: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection. Identification of any part found to have a defect and a description of the defect: NONE

Inspector and authenticator table: Name of Inspector: Jaafar Badr, Name of person authenticating this report: Hasan Omran, Latest date by which next thorough examination must be carried out: 06-06-2024





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Hilong Oil Services & Engineering, Rig Number, HL99, Job Number, ATS-12-23-2486

Table with 5 columns: Date of Examination, 07/12/2023, Date of Report, 07/12/2023, Certificate No, ATS-12-23-2486-MPI-024

Main equipment table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes.

Reference Standard table with columns: Reference Standard, LEEA DOC 048:2015, and examination frequency questions.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

NDT Equipment Details table with columns: Standard, API RP 4G CAT III & ASTM E709, Viewing Condition, Colored Media, Method, WET, Yoke, Vernier Caliper, White Contrast, Black Ink.

NDT Results section: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection. Identification of any part found to have a defect and a description of the defect: NONE. Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

Inspector and authenticator table with columns: Name of Inspector, Name of person authenticating this report, Signature & Stamp, Latest date by which next thorough examination must be carried out: 06-06-2024





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with client details: Client Name: Hilong Oil Services & Engineering, Rig Number: HL99, Job Number: ATS-12-23-2486

Table with examination details: Date of Examination: 07/12/2023, Date of Report: 07/12/2023, Certificate No: ATS-12-23-2486-MPI-025

Main table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes with dimensions and photos.

Reference Standard: LEEA DOC 048:2015. Inspection questions regarding examination frequency and installation correctness.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table for NDT Equipment Details including Standard, Yoke, Vernier Caliper, White Contrast, and Black Ink specifications.

NDT Results: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection. Identification of any part found to have a defect and a description of the defect: NONE

Inspector and authentication details: Name of Inspector: Jaafar Badr, Name of person authenticating this report: Hasan Omran, Latest date by which next thorough examination must be carried out: 06-06-2024





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with client details: Client Name: Hilong Oil Services & Engineering, Rig Number: HL99, Job Number: ATS-12-23-2486

Table with examination details: Date of Examination: 07/12/2023, Date of Report: 07/12/2023, Certificate No: ATS-12-23-2486-MPI-026

Main table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes and four photographs.

Reference Standard: LEEA DOC 048:2015. Inspection questions regarding examination frequency and installation correctness.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table for NDT Equipment Details including Standard, Yoke, Vernier Caliper, White Contrast, and Black Ink specifications.

NDT Results: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection. Identification of any part found to have a defect and a description of the defect: NONE

Table for inspector and authenticator details: Name of Inspector: Jaafar Badr, Name of person authenticating this report: Hasan Omran, Latest date by which next thorough examination must be carried out: 06-06-2024





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with client details: Client Name: Hilong Oil Services & Engineering, Rig Number: HL99, Job Number: ATS-12-23-2486

Table with examination details: Date of Examination: 07/12/2023, Date of Report: 07/12/2023, Certificate No: ATS-12-23-2486-MPI-027

Main equipment table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes and four photographs.

Reference Standard: LEEA DOC 048:2015. Inspection questions regarding examination frequency and installation correctness.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

NDT Equipment Details table listing standards (API RP 4G, ASTM E709), viewing conditions, media (Colored Media), methods (WET), and due dates for various tools like Yoke, Vernier Caliper, etc.

NDT Results: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection. Identification of any part found to have a defect and a description of the defect: NONE

Inspector and authenticator table: Name of Inspector: Jaafar Badr, Name of person authenticating this report: Hasan Omran, Latest date by which next thorough examination must be carried out: 06-06-2024





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with client details: Client Name: Hilong Oil Services & Engineering, Rig Number: HL99, Job Number: ATS-12-23-2486

Table with examination details: Date of Examination: 07/12/2023, Date of Report: 07/12/2023, Certificate No: ATS-12-23-2486-MPI-028

Main equipment table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes and four photographs.

Reference Standard: LEEA DOC 048:2015. Inspection questions regarding examination frequency and installation correctness.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with NDT Equipment Details including Standard, Viewing Condition, Colored Media, Method, and Due Date for various tools like Yoke, Vernier Caliper, etc.

NDT Results: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection. Identification of any part found to have a defect and a description of the defect: NONE

Inspector and authenticator information: Name of Inspector: Jaafar Badr, Name of person authenticating this report: Hasan Omran, Latest date by which next thorough examination must be carried out: 06-06-2024





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with client details: Client Name: Hilong Oil Services & Engineering, Rig Number: HL99, Job Number: ATS-12-23-2486

Table with examination details: Date of Examination: 07/12/2023, Date of Report: 07/12/2023, Certificate No: ATS-12-23-2486-MPI-029

Main table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for 'Fabricated Pad Eyes' and a photo of the equipment.

Reference Standard: LEEA DOC 048:2015. Inspection questions regarding examination frequency and installation correctness.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with NDT Equipment Details: Standard, Viewing Condition, Colored Media, Method, WET. Lists equipment like Yoke, Vernier Caliper, etc.

NDT Results: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection. Identification of any part found to have a defect and a description of the defect: NONE

Table with inspector details: Name of Inspector: Jaafar Badr, Name of person authenticating this report: Hasan Omran, Signature & Stamp, Latest date by which next thorough examination must be carried out: 06-06-2024





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Hilong Oil Services & Engineering, Rig Number, HL99, Job Number, ATS-12-23-2486

Table with 6 columns: Date of Examination, 07/12/2023, Date of Report, 07/12/2023, Certificate No, ATS-12-23-2486-MPI-030

Main inspection table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes and three photographs.

Reference Standard table with columns for questions and answers regarding examination frequency and installation correctness.

Defect identification table with columns for questions about defects and their severity, and a 'YES'/'NO' response column.

NDT Equipment Details table with columns for Standard, Viewing Condition, Colored Media, Method, and Due Date for various tools.

NDT Results table with columns for examination type and defect identification results.

Inspector and authenticator table with columns for Name of Inspector, Name of person authenticating this report, and Latest date by which next thorough examination must be carried out.





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Hilong Oil Services & Engineering, Rig Number, HL99, Job Number, ATS-12-23-2486

Table with 6 columns: Date of Examination, 07/12/2023, Date of Report, 07/12/2023, Certificate No, ATS-12-23-2486-MPI-030

Main equipment details table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes image of pad eye.


Reference Standard and examination questions table. Reference: LEEA DOC 048:2015. Questions about examination frequency and installation.

Defect identification table. Questions about defects and their severity. Includes 'IS THIS EQUIPMENT SAFE TO OPERATE?' section.

NDT Equipment Details table. Lists standards (API RP 4G, ASTM E709), viewing conditions, media, methods, and due dates for various tools.

NDT Results section. States 'Visual and MPI carried out for the above description and found free of surface defects at the time of inspection'.

Inspector and authenticator table. Name of Inspector: Jaafar Badr. Name of person authenticating: Hasan Omran. Latest date by which next thorough examination must be carried out: 06-06-2024.





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with client details: Client Name: Hilong Oil Services & Engineering, Rig Number: HL99, Job Number: ATS-12-23-2486

Table with examination details: Date of Examination: 07/12/2023, Date of Report: 07/12/2023, Certificate No: ATS-12-23-2486-MPI-031

Main equipment table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes and photos.

Reference Standard: LEEA DOC 048:2015. Inspection questions and answers regarding examination frequency and installation.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

NDT Equipment Details table listing standards (API RP 4G, ASTM E709), viewing conditions, media (Colored), methods (WET), and due dates for various tools.

NDT Results: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect: NONE

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

Inspector and authenticator table: Name of Inspector: Jaafar Badr, Name of person authenticating this report: Hasan Omran, Signature & Stamp, Latest date by which next thorough examination must be carried out: 06-06-2024





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Rig Number, Job Number, etc.

Table with 5 columns: Date of Examination, Date of Report, Certificate No, etc.

Main table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes image of pad eye.

Reference Standard table with columns for examination questions and answers.

Defect identification table with columns for defect description and safety status.

NDT Equipment Details table with columns for Standard, Viewing Condition, Method, etc.

NDT Results section with text describing the examination findings.

Inspector and authenticator table with columns for Name of Inspector, Name of person authenticating this report, etc.





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with client details: Client Name: Hilong Oil Services & Engineering, Rig Number: HL99, Job Number: ATS-12-23-2486

Table with examination details: Date of Examination: 07/12/2023, Date of Report: 07/12/2023, Certificate No: ATS-12-23-2486-MPI-034

Main equipment table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes and photos.

Reference Standard: LEEA DOC 048:2015. Inspection questions and results regarding examination frequency and safety.

Defect identification section: Identification of any part found to have a defect... IS THIS EQUIPMENT SAFE TO OPERATE?

NDT Equipment Details table listing standards (API RP 4G, ASTM E709), viewing conditions, media, and due dates for various tools.

NDT Results section: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection.

Inspector and authenticator information: Name of Inspector: Jaafar Badr, Name of person authenticating this report: Hasan Omran. Includes latest date for next examination: 06-06-2024.

