



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-28	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A6191 A6192 B6152	FOUR LEG WIRE ROPE SLINGE 22 mm Diameter, 8 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPliced WITH ALUMINUM FERRULE C/W MASTER LINK ASSEMBLY. Hard Eye X Soft Eye. FOS: 5:1 Location: Store	03	13 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 30.12.2023
---	--	--

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the 30.12.2023 above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-29	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A6420	<p>FOUR LEG WIRE ROPE SLINGE</p> <p>19 mm Diameter, 1.5 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPliced WITH ALUMINUM FERRULE C/W MASTER LINK ASSEMBLY. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: Store</p>	01	9.6 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:  30.12.2023
---	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the 30.12.2023 above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-30	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A7855	<p>FOUR LEG WIRE ROPE SLINGE</p> <p>12 mm Diameter, 2.6 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPliced WITH ALUMINUM FERRULE C/W MASTER LINK ASSEMBLY. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: Store</p>	01	3.53 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above mentioned equipment and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-31	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A10 A11 A12 A13	SINGLE LEG WIRE ROPE SLINGE 26 mm Diameter, 5.2 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Soft Eye. FOS: 5:1 Location: Store	04	8.6 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:  30.12.2023
---	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-32	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B6144 B6145 B6146 B6147	SINGLE LEG WIRE ROPE SLINGE 36 mm Diameter, 6 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	04	16.6 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
				Within an interval of 6 months?
				Within an interval of 12 months?
If the answer to the above question is YES has the equipment been installed correctly?				In accordance with an examination scheme?
				After the occurrence of exceptional circumstances?

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:
---	--	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-33	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A22 A23	SINGLE LEG WIRE ROPE SLINGE 32 mm Diameter, 6 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	02	116.1 KN
Reference Standards	BS EN 13414-1+A2:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:
--	--	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-34	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY18096890 GY18096886 GY18096894	SINGLE LEG WIRE ROPE SLINGE 22 mm Diameter, 12 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	03	54.9 KN

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:  30.12.2023
---	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-35	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A9620 A9621 A9622 A9623	SINGLE LEG WIRE ROPE SLINGE 30 mm Diameter, 6 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	04	16.6 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 30.12.2023
---	--	--

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the ~~above~~ **above** and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-36	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY18095899 GY18095900 GY18095901 GY18095902	SINGLE LEG WIRE ROPE SLINGE 26 mm Diameter, 6 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	04	7.6 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by **NO**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 30.12.2023
---	--	--

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-37	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY10096908 GY10096909	SINGLE LEG WIRE ROPE SLINGE 26 mm Diameter, 8.7 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	02	10 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:
---	--	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-38	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
15120 15121 15123 15126	SINGLE LEG WIRE ROPE SLINGE 22 mm Diameter, 10 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	04	5.65 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 30.12.2023
---	--	--

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-39	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
F001 F002 F003 F004	SINGLE LEG WIRE ROPE SLINGE 22 mm Diameter, 12 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	04	5.65 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
				Within an interval of 6 months?
				Within an interval of 12 months?
If the answer to the above question is YES has the equipment been installed correctly?				In accordance with an examination scheme?
				After the occurrence of exceptional circumstances?

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by **NO**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 30.12.2023
---	--	--

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-40	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL010 HL011 HL012 HL013	SINGLE LEG WIRE ROPE SLINGE 28 mm Diameter, 10 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	04	12.10 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 30.12.2023
---	--	--

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-41	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A11 A12	<p>SINGLE LEG WIRE ROPE SLINGE</p> <p>26 mm Diameter, 8.5 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye.</p> <p>FOS: 5:1 Location: Store</p>	02	6180 KG

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**


Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021