



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Rig Number, HL99, Job Number, ATs-12-23-2486

Table with 5 columns: Date of Examination, Date of Report, Certificate No, ATs-12-23-2486-MPI-055

Main table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes images of pad eyes.

Reference Standard table with columns for examination questions and YES/NO/checked boxes.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with 6 columns: Standard, Yoke, Vernier Caliper, White Contrast, Black Ink, and their respective details.

NDT Results section: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection. Identification of any part found to have a defect and a description of the defect: NONE. Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

Table with 2 columns: Name of Inspector, Name of person authenticating this report. Includes signatures and dates.

