



Certificate of Visual And Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name: Hilong Oil Services & Engineering Rig Number: HL-99 Job Number: ATS-12-23-2486

Date of Examination: 08-Jan-2024 Date of Report: 08-Jan-2024 Certificate No: ATS-12-23-2486-MPI-065

Table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough Examination. Includes details for OVERHEAD RUNWAY BEAM and photos of the equipment.

Reference Standard: ASME B30.17:2020 BS 2853:2011

Inspection questions and answers regarding installation and examination intervals.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with columns: Standard, Viewing Condition, Colored Media, Method, WET. Includes details for API RP 4G CAT III & ASTM E709.

NDT Results

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect: NONE

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

Inspector and authenticator information including names, signatures, and stamps.

