



# Aberdeen Technical Services and General Transportation

## Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	<b>Hilong Oil Services &amp; Engineering</b>	Certificate Number:	ATS-12-23-2486-MPI-067
Rig Number:	HL99	Job No:	ATS-12-23-2486
Location:	RIG-99/HILONG BASE	Page No:	01 of 01
Date of Inspection:	27-12-2023	Next Inspection Date:	26-06-2024
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444, ASTM A193

**PICTORIAL:**



**Item Description:**

Bolts, Studs, and Nuts

**Unit Serial Number: 170502**

**Details of inspection method(s):**  
Visible magnetic particle inspection

**Inspection Results:**  
MPI & VISUAL INSPECTION WAS CARRIED OUT ON CRITICAL AREAS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACK OR RELEVANT INDICATION AT THE TIME OF INSPECTION.

**Remarks:** **accepted**

Inspection Equipment Details			Personnel Details		Company Stamp
<b>Equipment</b>	Ac yoke		Inspector:	Aram Dlawar	
Serial Number	201504044		Qualifications	ASNT LEVEL II	
Calibration Date:	17-08-2023		Date:	27-12-2023	
Calibration Due:	16-02-2024		Signature:		
<b>Consumables</b>	MAGNETIC PARTICLES INSPECTION		Date:	31-12-2023	
Type:	WCP-4	Black magnetic ink-3			
Batch Number	L230523/1	L230125/3			
Expiry Date:	23-05-2028	25-1-2025			

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: [akader@aberdeents.com](mailto:akader@aberdeents.com)  
[inspection@aberdeents-iq.com](mailto:inspection@aberdeents-iq.com)

Tel: +964 7833334444 +964 782222633