



Certificate of Test and Thorough Examination of Lifting Equipment – Manual Chain Block

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Owner name and address:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination	26-Dec-2023
Location of Examination:	HILONG RIG 100	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-CB-04	Job Number:	ATS-12-23-2541
Date of Manufacture.:	-	Next Date of Examination:	25-June-2024
SWL:	3 TON	Serial No.:	923543
Description of equipment	<p><u>Manually Operated Chain Block</u></p> <p>Manufacture: Wuhuan Type / Model: 030 Chain Size: 8 mm Grade: 80 T8 Lifting Range: 3 M</p>		
Reference Standards	BS EN 14492-1:2006+A1:2009 / ASME B30.7		
Testing Details:	Pass	Fail	Notes
Functional (No Load)	√		Conducted and found satisfactory
Operational Test (Rated Capacity)	√		Conducted at rated capacity and found satisfactory
Light Load Test (2% - 10% x Rated Capacity)	√		Conducted at 5% of rated capacity and found satisfactory
Proof Load Test (1.5 x Rated Capacity)	N/A		-
Last Inspection Date	Next Inspection Due Date	Last Proof Load Test Date	Next Proof Load Test Due
-	25-June-2024	-	AFTER ANY REPAIR/MODIFICATION
Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out :		
	YES	NO	√
If the answer to the above question is YES has the equipment been installed correctly?	Within an interval of 6 months?		
	YES	NO	√
	Within an interval of 12 months?		
	YES	NO	√
	In accordance with an examination scheme?		
	YES	NO	√
	After the occurrence of exceptional circumstances?		
	YES	NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE)			
None			
Is the Above A Defect Which Is of Immediate Danger to Persons			YES
Is the Above A Defect Which Is Not Yet but Could Become A Danger to Persons: (If YES State the Date by When)			NO
Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			NO
None			NO
Particulars of Any Tests Carried Out as Part of The Examination: (If None State NONE)			
In the light of inspection findings chain block was Inspected visually, operationally, and functionally where no defects observed during the test. Hence, it was found satisfactory and fit for intended use.			
Is This Equipment Safe to Operate?		Yes Accept	No Reject
		√	√
Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:	
Syed Aamir Ali; ASNT LEVEL II VT, MT, PT, UT LEEA	Hasan Omran		

HIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this s tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found satisfactory at the time of inspection and considered Safe for Lifting.



Thorough Examination of Cahin Block - Checklist

Owner name and address:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination	26-Dec-2023
Location of Examination:	HILONG RIG 100	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-CB-04	Job Number:	ATS-12-23-2541
Date of Manufacture.:	-	Next Date of Examination:	25-June-2024
SWL:	3 TON	Serial No.:	923543

Inspected item / Point	Comments	Accept	Reject
Marking		√	
Body condition		√	
Casing		√	
Top hook		√	
Bottom hook		√	
Hooks safety latches		√	
Hooks swivel		√	
Load chain and Load Chain Sprockets		√	
Loose end anchor pins		√	
Hand chain and Hand chain wheel		√	
Side plates		√	
Brake operating condition		√	
Functionality of the chain hoist		√	

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
Syed Aamir Ali: ASNT LEVEL II VT, MT, PT, UT LEEA 	Hasan Omran	