



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Hilong Oil Services & Engineering, Rig Number, HL100, Job Number, ATS-12-23-2541

Table with 6 columns: Date of Examination, 23/12/2023, Date of Report, 23/12/2023, Certificate No, ATS-12-23-2541-MPI-020

Main equipment table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes and four photographs.

Reference Standard: LEEA DOC 048:2015. Inspection questions regarding examination frequency and installation correctness.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with 6 columns: Standard, API RP 4G CAT III & ASTM E709, Viewing Condition, Colored Media, Method, WET. Lists equipment like Yoke, Vernier Caliper, White Contrast, Black Ink.

NDT Results: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection. Identification of any part found to have a defect and a description of the defect: NONE

Inspector and authenticator information table. Includes Name of Inspector (Abdullah Mofeed), Name of person authenticating this report (Hasan Omran), and Latest date by which next thorough examination must be carried out: 22-06-2024.





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Hilong Oil Services & Engineering, Rig Number, HL100, Job Number, ATS-12-23-2541

Table with 6 columns: Date of Examination, 23/12/2023, Date of Report, 23/12/2023, Certificate No., ATS-12-23-2541-MPI-020

Main equipment details table with columns: Serial Number, QTY, Description, Clamp Total SWL, Date of last Thorough examination. Includes images of the pad eyes.

Reference Standard and examination questions table. Reference Standard: LEEA DOC 048:2015. Includes questions about examination frequency and safety.

NDT Equipment Details table with columns: Standard, API RP 4G CAT III & ASTM E709, Viewing Condition, Colored Media, Method, WET. Lists equipment like Yoke, Vernier Caliper, etc.

NDT Results section with text: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection.

Inspector and authenticator information table. Name of Inspector: Abdullah Mofeed, Name of person authenticating this report: Hasan Omran. Includes date for next examination: 22-06-2024.

