



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name: Hilong Oil Services & Engineering, Rig Number: HL-100, Job Number: ATS-12-23-2541

Date of Examination: 25-Dec-2023, Date of Report: 25-Dec-2023, Certificate No: ATS-12-23-2541-MPI-042

Table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes images of fabricated pad eyes.

Reference Standard: LEEA DOC 048:2015. Inspection questions regarding installation and examination intervals.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: NONE

Is the above a defect which is of immediate danger to persons: YES

Is the above a defect which is not yet but could become a danger to persons: N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES

Table with columns: Standard, Viewing Condition, Colored Media, Method, etc. for NDT Equipment Details.

NDT Results: ***Visual and MPI Carried Out For The Above Description and Found Free Of Surface Defects At The Time Of Inspection

Inspector: Syed Aamir Ali, Name of person authenticating this report: Hasan Omran, Signature & Stamp, Latest date by which next thorough examination must be carried out: 24-June-2024

