



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Rig Number, Job Number, etc. Values: Hilong Oil Services & Engineering, HL-100, ATN-12-23-2541

Table with 6 columns: Date of Examination, Date of Report, Certificate No. Values: 25-Dec-2023, 25-Dec-2023, ATN-12-23-2541-MPI-127

Main table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes description of 'Fabricated Pad Eyes' and photos.

Table with inspection questions and checkboxes. Questions include: 'Is this the first examination after Installation...', 'Was the examination carried out: Within an interval of 6 months?'

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with 6 columns: Standard, Viewing Condition, Method, etc. Details for Yoke, Vernier Caliper, White Contrast, Black Ink.

NDT Results
***Visual and MPI Carried Out For The Above Description and Found Free Of Surface Defects At The Time Of Inspection
***Identification Of Any Part Found To Have a Defect and a Description Of The Defect: NONE
***Particulars Of Any Repair, Renewal or Alteration Required To Remedy The Defect Identified Above: NONE

Table with 3 columns: Name of Inspector, Name of person authenticating this report, Signature & Stamp. Includes signature of Syed Aamir Ali and a circular stamp.

Latest date by which next thorough examination must be carried out: 24-June-2024