



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with client details: Client Name: Hilong Oil Services & Engineering, Rig Number: HL-100, Job Number: ATS-12-23-2541, Date of Examination: 25-Dec-2023, Date of Report: 25-Dec-2023, Certificate No: ATS-12-23-2541-MPI-133

Main examination table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes, thickness, pin hole, length, width, location, and S/N: 18070. Includes photographs of the equipment.

Reference Standard: LEEA DOC 048:2015. Inspection questions regarding installation and examination intervals with YES/NO/checked boxes.

Defect identification section: Identification of any part found to have a defect... Is the above a defect which is of immediate danger to persons? Is the above a defect which is not yet but could become a danger to persons?

Equipment safety and details section: IS THIS EQUIPMENT SAFE TO OPERATE? NDT Equipment Details table with columns: Standard, Viewing Condition, Colored Media, Method, Due Date.

NDT Results section: ***Visual and MPI Carried Out For The Above Description and Found Free Of Surface Defects At The Time Of Inspection. ***Identification Of Any Part Found To Have a Defect and a Description Of The Defect: NONE. ***Particulars Of Any Repair, Renewal or Alteration Required To Remedy The Defect Identified Above: NONE

Inspector and authenticator section: Name of Inspector: Syed Aamir Ali, Name of person authenticating this report: Hasan Omran, Signature & Stamp, Latest date by which next thorough examination must be carried out: 24-June-2024. Includes Aberdeen Technical Services stamp.