



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hilong Oil Services & Engineering	Rig Number:	HL-100	Job Number:	ATS-12-23-2541
Date of Examination:	25-Dec-2023	Date of Report:	25-Dec-2023	Certificate No:	ATS-12-23-2541-MPI-135
Serial Number:	QTY	Description	SWL	Date of last Thorough examination	
18072-5 18072-6 18072-7 18072-8	04	Fabricated Pad Eyes Pad Eye Dimension: Thickness: 25 mm Pin Hole: 50 mm Length: 315 mm Width: 250 mm Location: Production Water Tank (7) Lifting Pad Eye S/N: 18072	50 KN	Apr-2023	
Reference Standard:		LEEA DOC 048:2015			
Is this the first examination after Installation or assembly at a new site or location?		☐ YES ☒ NO		Was the examination carried out: Within an interval of 6 months? ☒ YES ☐ NO With an interval of 12 months? ☐ YES ☒ NO In accordance with an examination scheme? ☐ YES ☒ NO After the occurrence of exceptional circumstances? ☐ YES ☐ NO	
If the answer to the above question is YES has the equipment been installed correctly?		☐ YES ☒ NO		☐ YES ☐ NO	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				☐ YES ☐ NO ☒	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE					
IS THIS EQUIPMENT SAFE TO OPERATE?				☐ YES ☒ NO	
NDT Equipment Details					
Standard	API RP 4G CAT III & ASTM E709		Viewing Condition:	Colored Media	Method
Yoke	Permanent		Serial No:	PY-10	Due Date
Vernier Caliper	Digital		Serial No:	8914	Due Date
White Contrast	FLUXO: WCP-4		Batch No:	L230523/1	Due Date
Black Ink	FLUXO: Black magnetic ink-3		Batch No:	L230125/3	Due Date
NDT Results					
***Visual and MPI Carried Out For The Above Description and Found Free Of Surface Defects At The Time Of Inspection					
***Identification Of Any Part Found To Have a Defect and a Description Of The Defect: NONE					
***Particulars Of Any Repair, Renewal or Alteration Required To Remedy The Defect Identified Above: NONE					

Name of Inspector:	Name of person authenticating this report:	
Syed Aamir Ali	Hasan Omran	
	Signature & Stamp:	
Latest date by which next thorough examination must be carried out: 24-June-2024		