



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hilong Oil Services & Engineering	Rig Number:	HL-100	Job Number:	ATS-12-23-2541
Date of Examination:	25-Dec-2023	Date of Report:	25-Dec-2023	Certificate No:	ATS-12-23-2541-MPI-146

Serial Number:	QTY	Description	SWL	Date of last Thorough examination	
HL 01 HL 02 HL 03 HL 04	04	Fabricated Pad Eyes Pad Eye Dimension: Thickness: 10 mm Pin Hole: 35 mm Length: 120 mm Width: 85 mm Location: Rig Mud Saver Lifting Pad Eye S/N: HL - 003	1 Ton	Apr-2023	
Reference Standard:		LEEA DOC 048:2015			
Is this the first examination after Installation or assembly at a new site or location?		☐ YES ☒ NO		Was the examination carried out: Within an interval of 6 months? ☐ YES ☒ NO With an interval of 12 months? ☐ YES ☒ NO In accordance with an examination scheme? ☐ YES ☒ NO After the occurrence of exceptional circumstances? ☐ YES ☒ NO	
If the answer to the above question is YES has the equipment been installed correctly?		☐ YES ☒ NO			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				☐ YES ☒ NO	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE					
IS THIS EQUIPMENT SAFE TO OPERATE?				☐ YES ☒ NO	
NDT Equipment Details					
Standard	API RP 4G CAT III & ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-10	Due Date	17-Feb-2024
Vernier Caliper	Digital	Serial No:	8914	Due Date	16-Feb-2024
White Contrast	FLUXO: WCP-4	Batch No:	L230523/1	Due Date	23-May-2028
Black Ink	FLUXO: Black magnetic ink-3	Batch No:	L230125/3	Due Date	25-Jan-2025
NDT Results					
***Visual and MPI Carried Out For The Above Description and Found Free Of Surface Defects At The Time Of Inspection					
***Identification Of Any Part Found To Have a Defect and a Description Of The Defect: NONE					
***Particulars Of Any Repair, Renewal or Alteration Required To Remedy The Defect Identified Above: NONE					

Name of Inspector:	Name of person authenticating this report:	
Syed Aamir Ali	Hasan Omran	
	Signature & Stamp:	
Latest date by which next thorough examination must be carried out: 24-June-2024		