



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Rig Number, Job Number, etc. Values include Hilong Oil Services & Engineering, HL-100, and ATN-12-23-2541.

Table with 6 columns: Date of Examination, Date of Report, Certificate No. Values include 25-Dec-2023, 25-Dec-2023, and ATN-12-23-2541-MPI-147.

Main equipment details table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes images of the lifting pad eyes.

Inspection questions table with columns for YES/NO and checkmarks. Questions include 'Is this the first examination after Installation...' and 'Was the examination carried out: Within an interval of 6 months?'

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with 6 columns: Standard, Viewing Condition, Colored Media, Method, etc. Details include API RP 4G CAT III & ASTM E709, Colored Media, and WET.

NDT Results section containing three lines of text: '***Visual and MPI Carried Out For The Above Description...', '***Identification Of Any Part Found To Have a Defect...', and '***Particulars Of Any Repair, Renewal or Alteration Required To Remedy The Defect Identified Above: NONE

Inspector and authenticator table with columns: Name of Inspector, Name of person authenticating this report, Signature & Stamp, Latest date by which next thorough examination must be carried out.

