



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Hilong Oil Services & Engineering, Rig Number, HL100, Job Number, ATS-12-23-2541

Table with 6 columns: Date of Examination, 30/12/2023, Date of Report, 30/12/2023, Certificate No, ATS-12-23-2541-MPI-158

Main table with 5 columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for BP2, 01, Fabricated Pad Eyes, 3 TON, and a photo of the pad eye.

Reference Standard: LEEA DOC 048:2015

Table with 4 columns for inspection questions and their results (YES/NO/√).

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES √ NO

NDT Equipment Details

Table with 6 columns: Standard, API RP 4G CAT III & ASTM E709, Viewing Condition, Colored Media, Method, WET. Includes rows for Yoke, Vernier Caliper, White Contrast, and Black Ink.


NDT Results

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect: NONE

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

Table with 2 columns: Name of Inspector, Abdullah Mofeed; Name of person authenticating this report, Hasan Omran. Includes signature and stamp area.



Latest date by which next thorough examination must be carried out: 29-06-2024