



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with client details: Client Name: Hilong Oil Services & Engineering, Rig Number: HL100, Job Number: ATS-12-23-2541

Table with examination details: Date of Examination: 25/12/2023, Date of Report: 25/12/2023, Certificate No: ATS-12-23-2541-MPI-162

Main table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes with dimensions and photos.

Reference Standard: LEEA DOC 048:2015. Inspection questions regarding installation and examination intervals.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table for NDT Equipment Details with columns: Standard, Viewing Condition, Colored Media, Method, Yoke, Vernier Caliper, White Contrast, Black Ink.

NDT Results

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect: NONE

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

Table for inspector and authenticator: Name of Inspector: Syed Aamir Ali, Name of person authenticating this report: Hasan Omran, Signature & Stamp, Latest date by which next thorough examination must be carried out: 24-06-2024

