



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-32	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
1701 1702	BOW SHACKLE With HEX, Bolt, Nut, And Safety Cotter Pin: SIZE: 1 1/2" GRADE: 6 Manufactured: XW F.O.S: 6:1 Location: Store, <div style="text-align: center; margin-top: 10px;"> </div>	02	17 Ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?	YES	√	NO	
					Within an interval of 6 months?	YES		NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:									
Is the above a defect which is of immediate danger to persons						YES		NO	√
Is the above a defect which is not yet but could become a danger to persons						YES by			
Is this Equipment Fit for Purpose?						YES	√	NO	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None									
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:									

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT & LEEA	Authenticated By: Hassan Omran	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment


This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-33	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL 12	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/4" GRADE: 6 Manufactured: Kepro F.O.S: 6:1 Location: Store,</p> 	01	12 Ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?							
	YES		NO	√				
				Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		In accordance with an examination scheme?	YES	√	NO
					After the occurrence of exceptional circumstances?	YES		NO

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:				
Is the above a defect which is of immediate danger to persons	YES		NO	√
Is the above a defect which is not yet but could become a danger to persons	YES by			
Is this Equipment Fit for Purpose?	YES	√	NO	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None				
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:				

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT & LEEA	Hassan Omran	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-34	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL 95	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/8"</p> <p>GRADE: 6</p> <p>Manufactured: J & L</p> <p>F.O.S: 6:1</p> <p>Location: Store,</p> 	01	9 1/2 Ton
Reference Standards	BS EN 13889:2003+A1:2008		


Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons	YES		NO	√
Is the above a defect which is not yet but could become a danger to persons	YES by			
Is this Equipment Fit for Purpose?	YES	√	NO	

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT & LEEA	Hassan Omran	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-35	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
S 230	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 1/8" GRADE: 6 Manufactured: McKAT F.O.S: 6:1 Location: Store,</p> 	01	9 1/2 Ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Is this Equipment Fit for Purpose? YES √ NO

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT & LEEA	Hassan Omran	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment


This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-36	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A 4174 A 5286	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: Toyolift F.O.S: 6:1 Location: Store,</p> 	02	8 1/2 Ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
				√
				√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO	
				√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:			
Is the above a defect which is of immediate danger to persons	YES		NO
Is the above a defect which is not yet but could become a danger to persons	YES by		
Is this Equipment Fit for Purpose?	YES	√	NO
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None			
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:			

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT & LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021







Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-37	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL3 115	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1" GRADE: 6 Manufactured: J & L F.O.S: 6:1 Location: Store,</p> 	02	8 1/2 Ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:									
Is the above a defect which is of immediate danger to persons						YES		NO	√
Is the above a defect which is not yet but could become a danger to persons						YES by			
Is this Equipment Fit for Purpose?						YES	√	NO	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None									
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:									

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT & LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021







Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-38	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
F 1056 B	BOW SHACKLE With HEX, Bolt, Nut, And Safety Cotter Pin: SIZE: 1” GRADE: 6 Manufactured: Bash-P F.O.S: 6:1 Location: Store,	01	8 1/2 Ton
			
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:									
Is the above a defect which is of immediate danger to persons						YES		NO	√
Is the above a defect which is not yet but could become a danger to persons						YES by			
Is this Equipment Fit for Purpose?						YES	√	NO	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None									
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:									

Inspector Name, Qualifications & signature: <u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT & LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-39	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
113	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: SPYA F.O.S: 6:1 Location: Store,</p> 	01	8 1/2 Ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Is this Equipment Fit for Purpose? YES √ NO

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT & LEEA	Hassan Omran	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-40	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
888 017	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: DY F.O.S: 6:1 Location: Store,</p> 	02	6 1/2 Ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Is this Equipment Fit for Purpose? YES √ NO

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT & LEEA	Hassan Omran	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-41	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B4446	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4” GRADE: 6 Manufactured: Toyolift F.O.S: 6:1 Location: Store,</p> 	01	4 3/4 Ton
Reference Standards	BS EN 13889:2003+A1:2008		


Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons	YES		NO	√
Is the above a defect which is not yet but could become a danger to persons	YES by			
Is this Equipment Fit for Purpose?	YES	√	NO	

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT & LEEA	Hassan Omran	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-42	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
016 10	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8" GRADE: 6 Manufactured: J & L F.O.S: 6:1 Location: Store,</p> 	02	3 1/4 Ton
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Is this Equipment Fit for Purpose? YES √ NO

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT & LEEA	Hassan Omran	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment


This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	05-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2486-43	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2486	Next Date of Examination:	04-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
1212 1213	BOW SHACKLE With HEX, Bolt, Nut, And Safety Cotter Pin: SIZE: 5/8" GRADE: 6 Manufactured: Toyolift F.O.S: 6:1 Location: Store,	02	3 1/4 Ton
			
Reference Standards	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?										
	YES	NO	✓	Within an interval of 6 months?	YES	NO	✓	Within an interval of 12 months?	YES	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	✓	In accordance with an examination scheme?	YES	NO	✓	After the occurrence of exceptional circumstances?	YES	NO	✓

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:											
Is the above a defect which is of immediate danger to persons								YES	NO	✓	
Is the above a defect which is not yet but could become a danger to persons						YES by					
Is this Equipment Fit for Purpose?								YES	NO	✓	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None											
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:											

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT & LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021