



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with client details: Client Name (HILONG OIL SERVICE AND ENG CO, Iraq), Date of Examination (02-JAN-2024), Location of Examination (HILONG RIG 99), Date of Certificate (02-JAN-2024), Certificate Number (ATS-12-23-2486-45), Last Examination Date (N/A), Job Number (ATS-12-23-2486), Next Date of Examination (01-JULY-2024)

Table with equipment details: Serial No: / Asset No (112), Description of The Equipment (DEE SHACKLE With HEX. Bolt, Nut, and split Cotter Pin), Qty (01), SWL (6.5 Ton). Includes technical drawing of the shackle with dimensions L, D, C, B, A, H, M, F.

Reference Standards: BS EN 13889:2003+A1:2008

Table with examination questions: 'Is this the first examination after installation...', 'Was the examination carried out?', 'Within an interval of 6 months?', 'Within an interval of 12 months?', 'In accordance with an examination scheme?', 'After the occurrence of exceptional circumstances?'

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons: YES NO ✓

Is the above a defect which is not yet but could become a danger to persons: YES by

Is this Equipment Fit for Purpose? YES ✓ NO

Particulars of any repair, renewal or alteration required to remedy the defect identified above: None

Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:

Table with inspector and authenticator details: Inspector Name, Qualifications & signature (Mahmoud Ali, ASNT LEVEL II, VT,MT,PT,UT & LEEA), Authenticated By (Hassan Omran), Stamp and Date (Aberdeen Technical Services logo)

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with client details: Client Name (HILONG OIL SERVICE AND ENG CO, Iraq), Date of Examination (02-JAN-2024), Location of Examination (HILONG RIG 99), Date of Certificate (02-JAN-2024), Certificate Number (ATS-12-23-2486-46), Last Examination Date (N/A), Job Number (ATS-12-23-2486), Next Date of Examination (01-JULY-2024)

Table with equipment details: Serial No: / Asset No (A5066), Description of The Equipment (BOW SHACKLE With HEX. Bolt, Nut, and split Cotter Pin), Qty (01), SWL (6.5 Ton), Reference Standards (BS EN 13889:2003+A1:2008). Includes technical diagrams of the shackle.

Table with examination questions: 'Is this the first examination after installation...', 'Was the examination carried out?' with YES/NO columns and checkmarks.

Table with defect identification questions: 'Identification of any part found to have a defect...', 'Is the above a defect which is of immediate danger to persons?', 'Is the above a defect which is not yet but could become a danger to persons?', 'Is this Equipment Fit for Purpose?'.

Table with inspector and authenticator details: Inspector Name (Mahmoud Ali), ASNT LEVEL II, VT,MT,PT,UT & LEEA; Authenticated By (Hassan Omran); Stamp and Date (Aberdeen Technical Services seal).

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with client details: Client Name (HILONG OIL SERVICE AND ENG CO, Iraq), Date of Examination (02-JAN-2024), Location of Examination (HILONG RIG 99), Date of Certificate (02-JAN-2024), Certificate Number (ATS-12-23-2486-47), Last Examination Date (N/A), Job Number (ATS-12-23-2486), Next Date of Examination (01-JULY-2024)

Table with equipment details: Serial No./Asset No (B5628-B7999), Description of The Equipment (BOW SHACKLE With HEX. Bolt, Nut, and split Cotter Pin), Qty (08), SWL (4.75 Ton), Reference Standards (BS EN 13889:2003+A1:2008)

Table with examination questions: Was the examination carried out? Within an interval of 6 months? Within an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?

Table with defect identification: Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: Is the above a defect which is of immediate danger to persons? Is the above a defect which is not yet but could become a danger to persons? Is this Equipment Fit for Purpose?

Table with signatures: Inspector Name, Qualifications & signature (Mahmoud Ali, ASNT LEVEL II VT,MT,PT,UT & LEEA), Authenticated By (Hassan Omran), Stamp and Date (Aberdeen Technical Services stamp)

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021







## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	02-JAN-2024
<b>Location of Examination:</b>	HILONG RIG 99	<b>Date of Certificate:</b>	02-JAN-2024
<b>Certificate Number:</b>	ATS-12-23-2486-48	<b>Last Examination Date:</b>	N/A
<b>Job Number:</b>	ATS-12-23-2486	<b>Next Date of Examination:</b>	01-JULY-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B5632 B5633 B5635 B5634 B2021	<p align="center"><b><u>BOW SHACKLE</u></b></p> <p align="center"><b>With HEX. Bolt, Nut, and split Cotter Pin</b></p> <p><b>SIZE: 1"</b></p> <p><b>GRADE: 6</b></p> <p><b>Manufactured: TOYOLIFT</b></p> <p><b>F.O.S: 6:1</b></p> <p><b>Location: Store</b></p> 	05	8.5 Ton
<b>Reference Standards</b>	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:									
Is the above a defect which is of immediate danger to persons						YES		NO	√
Is the above a defect which is not yet but could become a danger to persons						YES by			
Is this Equipment Fit for Purpose?						YES	√	NO	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: <b>None</b>									
Particulars of any tests carried out as part of the examination: <b>Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:</b>									

<b>Inspector Name, Qualifications &amp; signature:</b>	<b>Authenticated By:</b>	<b>Stamp and Date:</b>
<b>Mahmoud Ali:</b> ASNT LEVEL II VT,MT,PT,UT & LEEA 	<b>Hassan Omran</b> 	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021







## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	02-JAN-2024
<b>Location of Examination:</b>	HILONG RIG 99	<b>Date of Certificate:</b>	02-JAN-2024
<b>Certificate Number:</b>	ATS-12-23-2486-49	<b>Last Examination Date:</b>	N/A
<b>Job Number:</b>	ATS-12-23-2486	<b>Next Date of Examination:</b>	01-JULY-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
D3073	<p align="center"><b><u>BOW SHACKLE</u></b></p> <p align="center"><b>With HEX. Bolt, Nut, and split Cotter Pin</b></p> <p><b>SIZE: 1"</b> <b>GRADE: 6</b> <b>Manufactured: BASH-P</b> <b>F.O.S: 6:1</b> <b>Location: Store</b></p> 	01	8.5 Ton
<b>Reference Standards</b>	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:									
Is the above a defect which is of immediate danger to persons						YES		NO	√
Is the above a defect which is not yet but could become a danger to persons						YES by			
Is this Equipment Fit for Purpose?						YES	√	NO	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: <b>None</b>									
Particulars of any tests carried out as part of the examination: <b>Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:</b>									

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Mahmoud Ali:</b> ASNT LEVEL II VT,MT,PT,UT & LEEA 	<b>Authenticated By:</b>  <b>Hassan Omran</b>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	02-JAN-2024
<b>Location of Examination:</b>	HILONG RIG 99	<b>Date of Certificate:</b>	02-JAN-2024
<b>Certificate Number:</b>	ATS-12-23-2486-50	<b>Last Examination Date:</b>	N/A
<b>Job Number:</b>	ATS-12-23-2486	<b>Next Date of Examination:</b>	01-JULY-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
FM0014	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX. Bolt, Nut, and split Cotter Pin</b></p> <p><b>SIZE:</b> 5/8"</p> <p><b>GRADE:</b> 6</p> <p><b>Manufactured:</b> J&amp;L</p> <p><b>F.O.S:</b> 6:1</p> <p><b>Location:</b> Store</p> 	01	3.25 Ton
<b>Reference Standards</b>	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Is this Equipment Fit for Purpose? YES √ NO

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
*Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:*

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Mahmoud Ali:</b> ASNT LEVEL II VT,MT,PT,UT & LEEA 	<b>Authenticated By:</b>  <b>Hassan Omran</b>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	02-JAN-2024
<b>Location of Examination:</b>	HILONG RIG 99	<b>Date of Certificate:</b>	02-JAN-2024
<b>Certificate Number:</b>	ATS-12-23-2486-51	<b>Last Examination Date:</b>	N/A
<b>Job Number:</b>	ATS-12-23-2486	<b>Next Date of Examination:</b>	01-JULY-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
110	<p align="center"><b><u>BOW SHACKLE</u></b></p> <p align="center"><b>With HEX. Bolt, Nut, and split Cotter Pin</b></p> <p><b>SIZE:</b> 7/8"</p> <p><b>GRADE:</b> 6</p> <p><b>Manufactured:</b> DSL</p> <p><b>F.O.S:</b> 6:1</p> <p><b>Location:</b> Store</p> 	01	6.5 Ton
<b>Reference Standards</b>	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Is this Equipment Fit for Purpose? YES  NO

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
*Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:*

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Mahmoud Ali:</b> ASNT LEVEL II VT,MT,PT,UT & LEEA 	<b>Authenticated By:</b>  <b>Hassan Omran</b>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment


This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	02-JAN-2024
<b>Location of Examination:</b>	HILONG RIG 99	<b>Date of Certificate:</b>	02-JAN-2024
<b>Certificate Number:</b>	ATS-12-23-2486-52	<b>Last Examination Date:</b>	N/A
<b>Job Number:</b>	ATS-12-23-2486	<b>Next Date of Examination:</b>	01-JULY-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
111	<p align="center"><b><u>BOW SHACKLE</u></b></p> <p align="center"><b>With HEX. Bolt, Nut, and split Cotter Pin</b></p> <p><b>SIZE:</b> 7/8" <b>GRADE:</b> 6 <b>Manufactured:</b> J&amp;L <b>F.O.S:</b> 6:1 <b>Location:</b> Store</p> 	01	6.5 Ton
<b>Reference Standards</b>	BS EN 13889:2003+A1:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:									
Is the above a defect which is of immediate danger to persons						YES		NO	√
Is the above a defect which is not yet but could become a danger to persons						YES by			
Is this Equipment Fit for Purpose?						YES	√	NO	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: <b>None</b>									
Particulars of any tests carried out as part of the examination: <b>Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:</b>									

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Mahmoud Ali:</b> ASNT LEVEL II VT,MT,PT,UT & LEEA 	<b>Authenticated By:</b>  <b>Hassan Omran</b>	<b>Stamp and Date:</b> 
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021