



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

| | | | |
|---------------------------------|--|----------------------------------|--------------|
| Client Name: | HILONG OIL SERVICE AND ENG CO, Iraq | Date of Examination: | 05-Dec-2023 |
| Location of Examination: | HILONG BASE RUMAILA | Date of Certificate: | 10-Dec-2023 |
| Certificate Number: | ATS-12-23-2486-028 | Last Examination Date: | Apr-2023 |
| Job Number: | ATS-12-23-2486 | Next Date of Examination: | 04-June-2024 |

| Serial No: / Asset No: | Description of The Equipment | Qty: | SWL: |
|------------------------|---|------|---------|
| A 8305 A 8306 | <p align="center"><u>TWO-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules</p> <p align="center">C/W Master Link on Top</p> <p align="center">Hard Eye At Both End</p> <p align="center">Dim: 13 mm (L) X 2 M</p> <p align="center">Location: Rig Floor,</p> <p align="center">F.O.S: 5:1</p> | 02 | 2.9 Ton |

| | |
|----------------------------|----------------------------|
| Reference Standards | BS EN 13414-1:2003+A2:2008 |
|----------------------------|----------------------------|

| | | | | | | | | | |
|---|-----|---|----|----------------------------------|--|-----|---|----|---|
| Is this the first examination after installation or assembly at a new site or location? | | | | Was the examination carried out? | | | | | |
| | YES | | NO | √ | Within an interval of 6 months? | YES | √ | NO | |
| If the answer to the above question is YES has the equipment been installed correctly? | | | | | Within an interval of 12 months? | YES | | NO | √ |
| | YES | √ | NO | | In accordance with an examination scheme? | YES | √ | NO | |
| | | | | | After the occurrence of exceptional circumstances? | YES | | NO | √ |

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

| | | | | |
|---|-----|--|----|---|
| Is the above a defect which is of immediate danger to persons | YES | | NO | √ |
|---|-----|--|----|---|

| | | | | |
|---|--------|--|--|--|
| Is the above a defect which is not yet but could become a danger to persons | YES by | | | |
|---|--------|--|--|--|

| | | | | |
|------------------------------------|-----|---|----|--|
| Is this Equipment Fit for Purpose? | YES | √ | NO | |
|------------------------------------|-----|---|----|--|

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:

| | | |
|---|---------------------------|------------------------|
| Inspector Name, Qualifications & signature: | Authenticated By: | Stamp and Date: |
| <p align="center"><u>Syed Aamir Ali:</u></p> <p align="center">ASNT LEVEL II</p> <p align="center">VT,MT,PT,UT</p> <p align="center">& LEEA</p> | <p>Hasan Omran</p> | |

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

| | | | |
|---------------------------------|--|----------------------------------|--------------|
| Client Name: | HILONG OIL SERVICE AND ENG CO, Iraq | Date of Examination: | 05-Dec-2023 |
| Location of Examination: | HILONG BASE RUMAILA | Date of Certificate: | 10-Dec-2023 |
| Certificate Number: | ATS-12-23-2486-029 | Last Examination Date: | Apr-2023 |
| Job Number: | ATS-12-23-2486 | Next Date of Examination: | 04-June-2024 |

| Serial No: / Asset No: | Description of The Equipment | Qty: | SWL: |
|------------------------|--|------|---------|
| B 4443 | <p><u>TWO-LEG WIRE ROPE SLING</u></p> <p>IWRC Mechanically Spliced with Aluminium Ferrules C/W Master Link on Top Hard Eye At Both End Dim: 10 mm (L) X 1.5 M Location: Rig Floor, F.O.S: 5:1</p> | 01 | 2.7 Ton |

| | |
|----------------------------|----------------------------|
| Reference Standards | BS EN 13414-1:2003+A2:2008 |
|----------------------------|----------------------------|

| | | | | | | | | | | | |
|---|-----|---|----|---|---|-----|---|--|-----|----|---|
| Is this the first examination after installation or assembly at a new site or location? | YES | | NO | √ | Was the examination carried out? | | | | | | |
| | | | | | Within an interval of 6 months? | YES | √ | NO | | | |
| If the answer to the above question is YES has the equipment been installed correctly? | | | | | Within an interval of 12 months? | YES | | NO | √ | | |
| | YES | √ | NO | | In accordance with an examination scheme? | YES | √ | NO | | | |
| | | | | | | | | After the occurrence of exceptional circumstances? | YES | NO | √ |

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

| | | | | |
|---|-----|--|----|---|
| Is the above a defect which is of immediate danger to persons | YES | | NO | √ |
|---|-----|--|----|---|

| | | |
|---|--------|--|
| Is the above a defect which is not yet but could become a danger to persons | YES by | |
|---|--------|--|

| | | | | |
|------------------------------------|-----|---|----|--|
| Is this Equipment Fit for Purpose? | YES | √ | NO | |
|------------------------------------|-----|---|----|--|

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:
Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection:

| | | |
|---|---|----------------------------|
| Inspector Name, Qualifications & signature: <p style="text-align: center;"><u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT & LEEA</p> | Authenticated By: <p style="text-align: center;">Hasan Omran</p> | Stamp and Date: |
|---|---|----------------------------|

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021

