



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-96	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
W261/32 W261/33	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced with Aluminium Ferrules Soft Eye At Both Ends, Dim: 36 mm (L) X 6 M F.O.S: 5:1	02	15 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?	YES	√	NO	
					Within an interval of 6 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIE-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-97	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
GY18096909	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Soft Eye At Both Ends, Dim: 26 mm (L) X 8 M F.O.S: 5:1</p>	01	16 KN

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-98	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
A 993 A 994 A 995 A 996 A 997 A 117 717	<p><u>SINGLE-LEG WIRE ROPE SLING</u></p> IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye At Both Ends, Dim: 16 mm (L) X 1.2 M F.O.S: 5:1	07	27 KN

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: <p style="text-align: center;"><u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA</p>	Authenticated By: <p style="text-align: center;">Hassan Omran</p>	Stamp and Date:
--	--	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the installation above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LTE-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-99	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
A 990	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye At Both Ends, Dim: 32 mm (L) X 6 M F.O.S: 5:1</p>	01	27 KN

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-100	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
A 10	<p><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p>IWRC Mechanically Spliced with Aluminium Ferrules Soft Eye At Both Ends, Dim: 26 mm (L) X 5.2 M F.O.S: 5:1</p>	01	13.1 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	✓
				Within an interval of 12 months? YES NO ✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	✓	NO	In accordance with an examination scheme? YES ✓ NO
				After the occurrence of exceptional circumstances? YES NO ✓

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons	YES		NO	✓
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	✓	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on 26-Dec-2023 and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-101	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
A 4212 A 4213	<p><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p>IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye At Both Ends, Dim: 16 mm (L) X 3.3 M F.O.S: 5:1</p>	02	3.3 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?						
					Within an interval of 6 months?	YES	√	NO			
				Within an interval of 12 months?				YES	NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO	In accordance with an examination scheme?				YES	√	NO	√
					After the occurrence of exceptional circumstances?				YES	NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: <p style="text-align: center;"><u>Syed Aamir Ali:</u> ASNT LEVEL II VT,MT,PT,UT LEEA</p>	Authenticated By: <p style="text-align: center;">Hassan Omran</p>	Stamp and Date:
---	--	--------------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-102	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
2201	<p><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p>IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye At Both Ends, Dim: 16 mm (L) X 1.2 M F.O.S: 5:1</p>	01	3.3 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?	YES	√	NO	
					Within an interval of 6 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operation Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LTF-F-002 ISSUE 2 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq /Rig 100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-103	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
GY180956882 GY180956883 GY180956884	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced with Aluminium Ferrules Soft Eye At Both Ends, Dim: 22 mm (L) X 12 M F.O.S: 5:1	03	54.9 KN

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting

ATS-LIE-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-104	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
1220 1221	<u>SINGLE-LEG WIRE ROPE SLING</u> IWRC Mechanically Spliced with Aluminium Ferrules Soft Eye At Both Ends, Dim: 16 mm (L) X 1.2 M F.O.S: 5:1	02	3.3 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-1-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-105	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
S 101/01	<p><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p>IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye with Plane End, Dim: 16 mm (L) X 90 M Location: Rig Air Winch F.O.S: 5:1</p>	01	2.7 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above-mentioned equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LTF-F:002-ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with 4 columns: Client Name, Location of Examination, Certificate Number, Job Number, Date of Examination, Date of Certificate, Last Examination Date, Next Date of Examination.

Table with 4 columns: Serial No. / Asset No., Description of The Equipment, Qty., SWL: (Includes details for SINGLE-LEG WIRE ROPE SLING)

Reference Standards: BS EN 13414-1:2003 + A2:2008

Table with columns for examination questions and Yes/No/Checkmark responses.

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:

Table with columns for defect identification and Yes/No/Checkmark responses.

Table with columns for defect identification and Yes/No/Checkmark responses.

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Table with columns for equipment fit for purpose and Yes/No/Checkmark responses.

Table with 3 columns: Inspector Name, Qualifications & signature; Authenticated By; Stamp and Date.

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location...

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-107	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
A 6240	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye At Both Ends, Dim: 19 mm (L) X 1.5 M F.O.S: 5:1</p>	01	9.6 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date stated above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-108	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
A 6192 A 8164	4-LEG WIRE ROPE SLING IWRC Mechanically Spliced with Aluminium Ferrules C/W Master Link on Top Hard Eye At Both End Dim: 22 mm (L) X 8 M F.O.S: 5:1	02	13 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations, Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-109	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
B 1264	<p align="center"><u>4-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules C/W Master Link on Top Hard Eye At Both End Dim: 16 mm (L) X 1.5 M F.O.S: 5:1</p>	01	6.9 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-110	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
15/107211	<p><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p>IWRC Mechanically Spliced with Aluminium Ferrules Hard Eye At Both Ends, Dim: 16 mm (L) X 2 M F.O.S: 5:1</p>	01	3.3 Ton

Reference Standards	BS EN 13414-1:2003 + A2:2008
----------------------------	------------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO
------------------------------------	-----	---	----

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting

ATS-LIF-E-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	25-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	10-Dec-2023
Certificate Number:	ATS-12-23-2541-111	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	24-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
GY18121734 GY18121735	<p align="center"><u>SINGLE-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Open Spelter Socket Open Spelter Socket X Plane End, Dim: 11 mm (L) X 66 M Location: Monkey Board, F.O.S: 5:1</p>	02	71.1 MBL

Reference Standards	BS EN 13414-1:2003+A2:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:


Is the above a defect which is of immediate danger to persons	YES		NO	√
---	-----	--	----	---

Is the above a defect which is not yet but could become a danger to persons	YES by	
---	--------	--

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination:

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date mentioned above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIE-F-002 ISSUE 3 - MAR 2021




Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	26-Dec-2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	27-Dec-2023
Certificate Number:	ATS-12-23-2541-112	Last Examination Date:	Sep-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	25-June-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL:
A 6190	<p align="center"><u>4-LEG WIRE ROPE SLING</u></p> <p align="center">IWRC Mechanically Spliced with Aluminium Ferrules C/W Master Link on Top Hard Eye At Both End Dim: 22 mm (L) X 6 M Location: Sewage Tank, F.O.S: 5:1</p>	01	13 Ton
Reference Standards	BS EN 13414-1:2003 + A2:2008		

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:									
Is the above a defect which is of immediate danger to persons						YES		NO	√
Is the above a defect which is not yet but could become a danger to persons						YES by			
Particulars of any repair, renewal or alteration required to remedy the defect identified above:									
Particulars of any tests carried out as part of the examination:									
Is this Equipment Fit for Purpose?						YES	√	NO	

Inspector Name, Qualifications & signature: Syed Aamir Ali: ASNT LEVEL II VT,MT,PT,UT LEEA	Authenticated By: Hassan Omran	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIE-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-113	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A11 A12	SINGLE LEG WIRE ROPE SLINGE 26 mm Diameter, 8.5 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	02	6180 KG
Reference Standards	BS EN 13414-1+A2:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None						
Is the above a defect which is of immediate danger to persons			YES		NO	
Is the above a defect which is not yet but could become a danger to persons			YES by			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None						
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.						

Is this Equipment Fit for Purpose?	YES	√	NO	
------------------------------------	-----	---	----	--

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:
--	--	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-114	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL010 HL011 HL012 HL013	SINGLE LEG WIRE ROPE SLINGE 28 mm Diameter, 10 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	04	12.10 ton
Reference Standards	BS EN 13414-1+A2:2008		

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: None						
Is the above a defect which is of immediate danger to persons			YES		NO	
Is the above a defect which is not yet but could become a danger to persons			YES by			
Particulars of any repair, renewal or alteration required to remedy the defect identified above: None						
Particulars of any tests carried out as part of the examination: Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.						

Is this Equipment Fit for Purpose?				YES	√	NO	
Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran			Stamp and Date:  30.12.2023			

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2541-115	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2541	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
F001 F002 F003 F004	SINGLE LEG WIRE ROPE SLINGE 22 mm Diameter, 12 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	04	5.65 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:
---	--	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date mentioned above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2542-116	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2542	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
15120 15121 15123 15126	SINGLE LEG WIRE ROPE SLINGE 22 mm Diameter, 10 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	04	5.65 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:
--	--	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2542-117	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2542	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY10096908 GY10096909	SINGLE LEG WIRE ROPE SLINGE 26 mm Diameter, 8.7 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	02	10 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 30.12.2023
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2542-119	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2542	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY18095899 GY18095900 GY18095901 GY18095902	SINGLE LEG WIRE ROPE SLINGE 26 mm Diameter, 6 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	04	7.6 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
				Within an interval of 6 months?
				Within an interval of 12 months?
If the answer to the above question is YES has the equipment been installed correctly?				In accordance with an examination scheme?
				After the occurrence of exceptional circumstances?

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:
--	--	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2542-119	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2542	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY18096890 GY18096886 GY18096894	SINGLE LEG WIRE ROPE SLINGE 22 mm Diameter, 12 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	03	54.9 KN

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date: 30.12.2023
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq / Rig 100	Date of Examination:	30.12.2023
Location of Examination:	HILONG BASE RUMAILA	Date of Certificate:	30.12.2023
Certificate Number:	ATS-12-23-2542-120	Last Examination Date:	Apr-2023
Job Number:	ATS-12-23-2542	Next Date of Examination:	29.06.2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A9620 A9621 A9622 A9623	SINGLE LEG WIRE ROPE SLINGE 30 mm Diameter, 6 M Length, Const.6x36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Soft Eye X Soft Eye. FOS: 5:1 Location: Store	04	16.6 ton

Reference Standards	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
				Within an interval of 6 months?
				Within an interval of 12 months?
If the answer to the above question is YES has the equipment been installed correctly?				In accordance with an examination scheme?
				After the occurrence of exceptional circumstances?

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES** **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above were inspected Visually and dimensionally where no signs of defects observed at the time of inspection.

Is this Equipment Fit for Purpose? **YES** **NO**

Inspector Name, Qualifications & signature: Khaled Mahmoud: ASNT LEVEL II VT, MT, PT, UT LEEA	Authenticated By: Hasan Omran	Stamp and Date:
--	--	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021

