



**Certificate of Test and Thorough Examination of Lifting Equipment – Manual Chain Block**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Owner name and address:</b>	HILONG OIL SERVICE AND ENG CO, Iraq	<b>Date of Examination</b>	28-02-2024
<b>Location of Examination:</b>	HILONG RIG 99 / RU - 573	<b>Date of Certificate:</b>	28-02-2024
<b>Certificate Number:</b>	ATS-02-24-2997-CB-001	<b>Job Number:</b>	ATS-02-24-2997
<b>Date of Manufacture.:</b>	2022	<b>Next Date of Examination:</b>	27-08-2024
<b>SWL:</b>	3 TON	<b>Serial No.:</b>	22
<b>Description of equipment</b>	<p><b><u>Manually Operated Chain Block</u></b></p> <p>Manufacture: BEI JING            Type / Model: HSZ            Chain Size: 8 mm            Grade: 80 / T8            Lifting Range: 3 M</p>		
<b>Reference Standards</b>	BS EN 13157:2004+A1:2009 / ASME B30.7		
<b>Testing Details:</b>	<b>Pass</b>	<b>Fail</b>	<b>Notes</b>
<b>Functional (No Load)</b>	√		Conducted and found satisfactory
<b>Operational Test (Rated Capacity)</b>	√		Conducted at rated capacity and found satisfactory
<b>Light Load Test (2% - 10% x Rated Capacity)</b>	√		Conducted at 5% of rated capacity and found satisfactory
<b>Proof Load Test (1.5 x Rated Capacity)</b>	N/A		-
<b>Last Inspection Date</b>	<b>Next Inspection Due Date</b>	<b>Last Proof Load Test Date</b>	<b>Next Proof Load Test Due</b>
-	27-08-2024	-	AFTER ANY REPAIR/MODIFICATION
Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out:		
	YES	NO	√
If the answer to the above question is YES has the equipment been installed correctly?	Within an interval of 6 months?		
	YES	NO	√
	Within an interval of 12 months?		
	YES	NO	√
	In accordance with an examination scheme?		
	YES	NO	√
	After the occurrence of exceptional circumstances?		
	YES	NO	√
<b>Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect:</b> (If none state NONE) <b>None</b>			
Is the Above A Defect Which Is of Immediate Danger to Persons			YES
Is the Above A Defect Which Is Not Yet but Could Become A Danger to Persons: (If YES State the Date by When)			NO
<b>Particulars of Any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:</b> <b>None</b>			
<b>Particulars of Any Tests Carried Out as Part of The Examination: (If None State NONE)</b> In the light of inspection findings chain block was Inspected visually, operationally, and functionally where no defects observed during the test. Hence, it was found satisfactory and fit for intended use.			
<b>Is This Equipment Safe to Operate?</b>		Yes Accept	No Reject
		√	
<b>Inspector Name, Qualifications &amp; signature:</b>	<b>Authenticated By:</b>	<b>Stamp and Date:</b>	
<b>Hasan Omran</b> NDT Level II (VT, MT, PT, UT) LEEA Registered Technician	<b>Majd Dayoub</b>		

**HIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this s tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





**Thorough Examination of Cahin Block - Checklist**

<b>Owner name and address:</b>	HILONG OIL SERVICE AND ENG CO, Iraq	<b>Date of Examination</b>	28-Feb-2024
<b>Location of Examination:</b>	HILONG RIG 99 – RU-573	<b>Date of Certificate:</b>	28-Feb-2024
<b>Certificate Number:</b>	ATS-02-24-2997-CB-001	<b>Job Number:</b>	ATS-02-24-2997
<b>Date of Manufacture.:</b>	2022	<b>Next Date of Examination:</b>	27-Aug-2024
<b>SWL:</b>	3 TON	<b>Serial No.:</b>	22

Inspected item / Point	Comments	Accept	Reject
Marking		√	
Body condition		√	
Casing		√	
Top hook		√	
Bottom hook		√	
Hooks safety latches		√	
Hooks swivel		√	
Load chain and Load Chain Sprockets		√	
Loose end anchor pins		√	
Hand chain and Hand chain wheel		√	
Side plates		√	
Brake operating condition		√	
Functionality of the chain hoist		√	

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
<p><b>Hasan Omran</b>                      NDT Level II (VT, MT, PT, UT)                      LEEA Registered Technician</p> 	<p><b>Majd Dayoub</b></p>	

