




Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100 / Northern Rumila – R707	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-001	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
1006/A	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 ¼”</p> <p>GRADE: 6</p> <p>Manufactured: GP</p> <p>F.O.S: 6:1</p> 	1	12 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center"><i>ASNT LEVEL II (VT, MT, PT, UT)</i></p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center"><i>Majd Dayoub</i></p>	Stamp and Date: 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF F-002 ISSUE 3 - MAR 2021






Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-002	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
020B03	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1 ¼"</p> <p>GRADE: 6</p> <p>Manufactured: HK</p> <p>F.O.S: 6:1</p> 	1	12 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><i>[Signature]</i></p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p> <p align="center"><i>[Signature]</i></p>	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100 / Northern Rumila – R707	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-003	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B6150 B6151 B6149 B6148	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: TOYOLIFT F.O.S: 6:1</p> 	4	6.5 Ton

Reference Standards BS EN 13889:2003 + A1:2008

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: Hasan Omran <i>(Signature)</i> ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	Authenticated By: Majd Dayoub <i>(Signature)</i>	Stamp and Date: 
---	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100 / Northern Rumila – R707	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-004	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
11 108 H2 H4 H6 FS11 H8 H9 1100 106	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8"</p> <p>GRADE: 6</p> <p>Manufactured: J & L</p> <p>F.O.S: 6:1</p> 	10	3.25 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date: 
---	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100 / Northern Rumila – R707	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-005	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
107 A53 109 101 HL87 B3 112 A107	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8" GRADE: 6 Manufactured: J & L F.O.S: 6:1</p>	8	3.25 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center"><i>(Signature)</i></p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center"><i>(Signature)</i></p> <p align="center">Majd Dayoub</p>	Stamp and Date:
---	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100 / Northern Rumila – R707	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-006	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
107 A53 109 101 HL87 B3 112 A107	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8"</p> <p>GRADE: 6</p> <p>Manufactured: J & L</p> <p>F.O.S: 6:1</p>	8	3.25 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date:

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location, on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100 / Northern Rumila – R707	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-007	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H5	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8” GRADE: 6 Manufactured: DSL F.O.S: 6:1</p> 	1	6.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center"><i>(Signature)</i></p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center"><i>(Signature)</i></p> <p align="center">Majd Dayoub</p>	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100 / Northern Rumila – R707	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-008	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
K85	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: GT6 F.O.S: 6:1</p> 	1	8.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
<p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	<p align="center">Majd Dayoub</p> 	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100 / Northern Rumila – R707	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-009	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
R143	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: CROSBY F.O.S: 6:1</p>	1	6.5 Ton

Reference Standards BS EN 13889:2003 + A1:2008

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date:
---	--	--------------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations, Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100 / Northern Rumila – R707	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-010	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A2 H3 H11	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4”</p> <p>GRADE: 6</p> <p>Manufactured: J & L</p> <p>F.O.S: 6:1</p> 	3	4.75 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date: 
---	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100 / Northern Rumila – R707	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-011	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H10	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4” GRADE: 6 Manufactured: DY F.O.S: 6:1</p> 	1	4.75 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><i>[Signature]</i></p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p> <p align="center"><i>[Signature]</i></p>	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100 / Northern Rumila – R707	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-012	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
13	<p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8" GRADE: 6 Manufactured: DY F.O.S: 6:1</p>	1	3.25 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center"><i>(Signature)</i></p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center"><i>(Signature)</i></p> <p align="center">Majd Dayoub</p>	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100 / Northern Rumila – R707	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-013	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
A3512	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: TOYOLIFT F.O.S: 6:1</p> 	1	8.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center"><i>(Signature)</i></p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center"><i>(Signature)</i></p> <p align="center">Majd Dayoub</p>	Stamp and Date: 
--	---	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100 / Northern Rumila – R707	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-014	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
2HS	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: CROSBY F.O.S: 6:1</p> 	1	8.5 Ton

Reference Standards BS EN 13889:2003 + A1:2008

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date: 
--	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	26-03-2024
Location of Examination:	HL100 / Northern Rumila – R707	Date of Certificate:	26-03-2024
Certificate Number:	ATS-03-24-3078-015	Last Examination Date:	-
Job Number:	ATS-03-24-3078	Next Date of Examination:	25-09-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
D7332	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8" GRADE: 6 Manufactured: BASH-D F.O.S: 6:1</p>	1	6.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO √

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES √ NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center"><i>(Signature)</i></p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center"><i>(Signature)</i></p> <p align="center">Majd Dayoub</p>	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF F-002 ISSUE 3 - MAR 2021