




Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

| | | | |
|---------------------------------|--|----------------------------------|------------|
| Client Name: | HILONG OIL SERVICE AND ENG CO, Iraq | Date of Examination: | 26-03-2024 |
| Location of Examination: | HL100 / Northern Rumila – R707 | Date of Certificate: | 26-03-2024 |
| Certificate Number: | ATS-03-24-3078-016 | Last Examination Date: | - |
| Job Number: | ATS-03-24-3078 | Next Date of Examination: | 25-09-2024 |

| Serial No: / Asset No: | Description of The Equipment | Qty: | SWL |
|------------------------|--|------|----------|
| 111 | <p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8" GRADE: 6 Manufactured: NA F.O.S: 6:1</p>  | 1 | 3.25 Ton |

Reference Standards BS EN 13889:2003 + A1:2008

| | | | | | | | | | |
|---|-----|---|----|----------------------------------|--|-----|---|----|---|
| Is this the first examination after installation or assembly at a new site or location? | | | | Was the examination carried out? | | | | | |
| | YES | | NO | ✓ | Within an interval of 6 months? | YES | ✓ | NO | |
| If the answer to the above question is YES has the equipment been installed correctly? | YES | ✓ | NO | | Within an interval of 12 months? | YES | | NO | ✓ |
| | | | | | In accordance with an examination scheme? | YES | ✓ | NO | |
| | | | | | After the occurrence of exceptional circumstances? | YES | | NO | ✓ |

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **No manufacturer name, symbol, or traceability code**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **remove from service**

Particulars of any tests carried out as part of the examination:
Items mentioned-above was inspected Visually at the time of inspection

Is this Equipment Fit for Purpose? YES NO

| | | |
|---|--|---|
| Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p> | Authenticated By: <p align="center">Majd Dayoub</p> | Stamp and Date:  |
|---|--|---|

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Unsatisfactory** at the time of Inspection and considered **Unsafe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

| | | | |
|---------------------------------|--|----------------------------------|------------|
| Client Name: | HILONG OIL SERVICE AND ENG CO, Iraq | Date of Examination: | 26-03-2024 |
| Location of Examination: | HL100 / Northern Rumila – R707 | Date of Certificate: | 26-03-2024 |
| Certificate Number: | ATS-03-24-3078-017 | Last Examination Date: | - |
| Job Number: | ATS-03-24-3078 | Next Date of Examination: | 25-09-2024 |

| Serial No: / Asset No: | Description of The Equipment | Qty: | SWL |
|------------------------|---|------|----------|
| K52 K53 | <p align="center">DEE SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 5/8” GRADE: 6 Manufactured: NA F.O.S: 6:1</p>  | 2 | 3.25 Ton |

Reference Standards BS EN 13889:2003 + A1:2008

| | | | | | | | | | |
|---|-----|---|----|--|---|-----|----|----|---|
| Is this the first examination after installation or assembly at a new site or location? | | | | | Was the examination carried out? | | | | |
| | YES | | NO | ✓ | Within an interval of 6 months? | YES | ✓ | NO | |
| If the answer to the above question is YES has the equipment been installed correctly? | YES | ✓ | NO | | Within an interval of 12 months? | YES | | NO | ✓ |
| | | | | | In accordance with an examination scheme? | YES | ✓ | NO | |
| | | | | After the occurrence of exceptional circumstances? | YES | | NO | ✓ | |

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **no manufacturer & stuck nut**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **remove from service**

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually at the time of inspection

Is this Equipment Fit for Purpose? YES NO

| | | |
|---|---|---|
| Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician | Authenticated By: Majd Dayoub | Stamp and Date:  |
|---|---|---|

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Unsatisfactory** at the time of Inspection and considered **Unsafe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

| | | | |
|---------------------------------|--|----------------------------------|------------|
| Client Name: | HILONG OIL SERVICE AND ENG CO, Iraq | Date of Examination: | 26-03-2024 |
| Location of Examination: | HL100 / Northern Rumila – R707 | Date of Certificate: | 26-03-2024 |
| Certificate Number: | ATS-03-24-3078-018 | Last Examination Date: | - |
| Job Number: | ATS-03-24-3078 | Next Date of Examination: | 25-09-2024 |

| Serial No: / Asset No: | Description of The Equipment | Qty: | SWL |
|------------------------|--|------|----------|
| B2217 B2213 | <p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4” GRADE: 6 Manufactured: TOYOLIFT F.O.S: 6:1</p> | 2 | 4.75 Ton |

| | |
|----------------------------|----------------------------|
| Reference Standards | BS EN 13889:2003 + A1:2008 |
|----------------------------|----------------------------|

| | | | | | | | | | |
|---|-----|---|----|---|--|-----|---|----|---|
| Is this the first examination after installation or assembly at a new site or location? | | | | | Was the examination carried out? | | | | |
| | YES | | NO | ✓ | Within an interval of 6 months? | YES | ✓ | NO | |
| If the answer to the above question is YES has the equipment been installed correctly? | YES | ✓ | NO | | Within an interval of 12 months? | YES | | NO | ✓ |
| | | | | | In accordance with an examination scheme? | YES | ✓ | NO | |
| | | | | | After the occurrence of exceptional circumstances? | YES | | NO | ✓ |

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **worn body**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **remove from service**

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

| | | |
|---|--|----------------------------|
| Inspector Name, Qualifications & signature: Hasan Omran ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician | Authenticated By: Majd Dayoub | Stamp and Date: |
|---|--|----------------------------|

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Unsatisfactory** at the time of Inspection and considered **Unsafe** for Lifting.

ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with client details: Client Name (HILONG OIL SERVICE AND ENG CO, Iraq), Location of Examination (HL100 / Northern Rumila - R707), Certificate Number (ATS-03-24-3078-019), Job Number (ATS-03-24-3078), Date of Examination (26-03-2024), Date of Certificate (26-03-2024), Last Examination Date (-), Next Date of Examination (25-09-2024)

Table with equipment details: Serial No: / Asset No: H1, Description of The Equipment: BOW SHACKLE With HEX, Bolt, Nut, And Safety Cotter Pin, Qty: 1, SWL: 13.5 Ton. Includes technical diagrams of the shackle.

Reference Standards: BS EN 13889:2003 + A1:2008

Table with inspection questions: 'Is this the first examination after installation...', 'Was the examination carried out?', 'In accordance with an examination scheme?', 'After the occurrence of exceptional circumstances?'

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: No manufacturer

Is the above a defect which is of immediate danger to persons: YES, NO

Is the above a defect which is not yet but could become a danger to persons: YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: remove from service

Particulars of any tests carried out as part of the examination: visual inspection: Items mentioned-above was inspected Visually at the time of inspection

Is this Equipment Fit for Purpose?: YES, NO

Table with inspector and authenticator details: Inspector Name, Qualifications & signature (Hasan Omran, ASNT LEVEL II, LEEA Registered Technician), Authenticated By (Majd Dayoub), Stamp and Date (Aberdeen Technical Services)

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Unsatisfactory at the time of Inspection and considered Unsafe for Lifting.

ATS-LIF F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

| | | | |
|---------------------------------|--|----------------------------------|------------|
| Client Name: | HILONG OIL SERVICE AND ENG CO, Iraq | Date of Examination: | 26-03-2024 |
| Location of Examination: | HL100 / Northern Rumila – R707 | Date of Certificate: | 26-03-2024 |
| Certificate Number: | ATS-03-24-3078-020 | Last Examination Date: | - |
| Job Number: | ATS-03-24-3078 | Next Date of Examination: | 25-09-2024 |

| Serial No: / Asset No: | Description of The Equipment | Qty: | SWL |
|------------------------|---|------|----------|
| B5305 | <p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4” GRADE: 6 Manufactured: TOYOLIFT F.O.S: 6:1</p> | 1 | 4.75 Ton |

Reference Standards BS EN 13889:2003 + A1:2008

| | | | | | | | | | |
|---|-----|---|----|--|---|-----|----|----|---|
| Is this the first examination after installation or assembly at a new site or location? | | | | | Was the examination carried out? | | | | |
| | YES | | NO | ✓ | Within an interval of 6 months? | YES | ✓ | NO | |
| If the answer to the above question is YES has the equipment been installed correctly? | YES | ✓ | NO | | Within an interval of 12 months? | YES | | NO | ✓ |
| | | | | | In accordance with an examination scheme? | YES | ✓ | NO | |
| | | | | After the occurrence of exceptional circumstances? | YES | | NO | ✓ | |

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **worn body**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **remove from service**

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

| | | |
|---|--|----------------------------|
| Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p> | Authenticated By: <p align="center">Majd Dayoub</p> | Stamp and Date: |
|---|--|----------------------------|

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Unsatisfactory** at the time of Inspection and considered **Unsafe** for Lifting.

ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Table with client details: Client Name (HILONG OIL SERVICE AND ENG CO, Iraq), Location of Examination (HL100 / Northern Rumila - R707), Certificate Number (ATS-03-24-3078-021), Job Number (ATS-03-24-3078), Date of Examination (26-03-2024), Date of Certificate (26-03-2024), Last Examination Date (-), Next Date of Examination (25-09-2024)

Table with equipment details: Serial No: / Asset No: H7, Description of The Equipment: BOW SHACKLE With HEX, Bolt, Nut, And Safety Cotter Pin, Qty: 1, SWL: 4.75 Ton. Includes technical drawings of the shackle.

Reference Standards: BS EN 13889:2003 + A1:2008

Table with inspection questions: Was the examination carried out? Within an interval of 6 months? Within an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: Stuck Nut

Is the above a defect which is of immediate danger to persons: YES

Is the above a defect which is not yet but could become a danger to persons: YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: remove from service

Particulars of any tests carried out as part of the examination: visual inspection: Items mentioned-above was inspected Visually at the time of inspection

Is this Equipment Fit for Purpose? YES

Inspector Name, Qualifications & signature: Hasan Omran, ASNT LEVEL II (VT, MT, PT, UT), LEEA Registered Technician. Authenticated By: Majd Dayoub. Stamp and Date: ABERDEEN TECHNICAL SERVICES logo.

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Unsatisfactory at the time of Inspection and considered Unsafe for Lifting.

ATS-LIF F-002 ISSUE 3 - MAR 2021





Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

| | | | |
|---------------------------------|--|----------------------------------|------------|
| Client Name: | HILONG OIL SERVICE AND ENG CO, Iraq | Date of Examination: | 26-03-2024 |
| Location of Examination: | HL100 / Northern Rumila – R707 | Date of Certificate: | 26-03-2024 |
| Certificate Number: | ATS-03-24-3078-022 | Last Examination Date: | - |
| Job Number: | ATS-03-24-3078 | Next Date of Examination: | 25-09-2024 |

| Serial No: / Asset No: | Description of The Equipment | Qty: | SWL |
|------------------------|---|------|---------|
| HS85 | <p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8” GRADE: 6 Manufactured: NA F.O.S: 6:1</p> | 1 | 6.5 Ton |

| | |
|----------------------------|----------------------------|
| Reference Standards | BS EN 13889:2003 + A1:2008 |
|----------------------------|----------------------------|

| | | | | | | | | | |
|---|-----|---|----|---|--|-----|---|----|---|
| Is this the first examination after installation or assembly at a new site or location? | | | | | Was the examination carried out? | | | | |
| | YES | | NO | ✓ | Within an interval of 6 months? | YES | ✓ | NO | |
| If the answer to the above question is YES has the equipment been installed correctly? | YES | ✓ | NO | | Within an interval of 12 months? | YES | | NO | ✓ |
| | | | | | In accordance with an examination scheme? | YES | ✓ | NO | |
| | | | | | After the occurrence of exceptional circumstances? | YES | | NO | ✓ |

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **No manufacturer**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **remove from service**

Particulars of any tests carried out as part of the examination: visual inspection:
 Items mentioned-above was inspected Visually at the time of inspection

Is this Equipment Fit for Purpose? YES NO

| | | |
|---|--|----------------------------|
| Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p> | Authenticated By: <p align="center">Majd Dayoub</p> | Stamp and Date: |
|---|--|----------------------------|

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Unsatisfactory** at the time of Inspection and considered **Unsafe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021