



## Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

|              |                                   |             |        |             |                |
|--------------|-----------------------------------|-------------|--------|-------------|----------------|
| Client Name: | Hilong Oil Services & Engineering | Rig Number: | HL-101 | Job Number: | ATS-04-24-3079 |
|--------------|-----------------------------------|-------------|--------|-------------|----------------|

|                      |            |                 |            |                 |                           |
|----------------------|------------|-----------------|------------|-----------------|---------------------------|
| Date of Examination: | 12-04-2024 | Date of Report: | 12-04-2024 | Certificate No: | ATS-04-24-3079- MPI-04/25 |
|----------------------|------------|-----------------|------------|-----------------|---------------------------|

| Pad Eyes S/N:                                                                      | QTY | Description                                                                                                                                                                                                                 | SWL   | Date of last Thorough examination |
|------------------------------------------------------------------------------------|-----|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------|-----------------------------------|
| 1-1<br>1-2<br>1-3<br>1-4                                                           | 04  | <b>Fabricated Pad Eyes</b><br><br><b>Pad Eye Dimension</b><br><br><b>Thickness:</b> 25 mm<br><b>Pin Hole :</b> 40 mm<br><b>Height:</b> 97 mm<br><b>Length:</b> 170 mm<br><b>Location :</b> Bop Lifting Device No: BHD230601 | 2 Ton | New                               |
|  |     |                                                                                                                                                                                                                             |       |                                   |

**Reference Standard:** LEEA DOC 048:2015

|                                                                                         |     |    |   |                                                                     |     |    |   |
|-----------------------------------------------------------------------------------------|-----|----|---|---------------------------------------------------------------------|-----|----|---|
| Is this the first examination after Installation or assembly at a new site or location? | YES | NO | √ | Was the examination carried out:<br>Within an interval of 6 months? | YES | NO | √ |
|                                                                                         |     |    |   | With an interval of 12 months?                                      | YES | NO | √ |
| If the answer to the above question is YES has the equipment been installed correctly?  | YES | NO |   | In accordance with an examination scheme?                           | YES | NO | √ |
|                                                                                         |     |    |   | After the occurrence of exceptional circumstances?                  | YES | NO | √ |

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

**IS THIS EQUIPMENT SAFE TO OPERATE?** YES √ NO

### NDT Equipment Details

| Standard        | API RP 4G CAT III & ASTM E709 | Viewing Condition: | Colored Media | Method   | WET        |
|-----------------|-------------------------------|--------------------|---------------|----------|------------|
| Yoke            | AC                            | Serial No:         | 201504044     | Due Date | 04-07-2024 |
| Vernier Caliper | Digital                       | Serial No:         | 8914          | Due Date | 04-07-2024 |
| White Contrast  | FLUXO: WCP-4                  | Batch No:          | L230523/1     | Due Date | 23-05-2028 |
| Black Ink       | FLUXO: Black magnetic ink-3   | Batch No:          | L230125/3     | Due Date | 25-1-2025  |

### NDT Results

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect: **NONE**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

|                                                                                |                                            |
|--------------------------------------------------------------------------------|--------------------------------------------|
| Name of Inspector:                                                             | Name of person authenticating this report: |
| Jaa far Badr                                                                   | Hasan Omran                                |
|                                                                                | Signature & Stamp:                         |
| Latest date by which next thorough examination must be carried out: 11-10-2024 |                                            |

