



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Hilong Oil Services & Engineering, Rig Number, HL-101, Job Number, ATS-04-24-3079

Table with 6 columns: Date of Examination, 12-04-2024, Date of Report, 12-04-2024, Certificate No, ATS-04-24-3079- MPI-04/28

Main equipment table with columns: Pad Eyes S/N, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes and four photographs.

Reference Standard: LEEA DOC 048:2015

Table with inspection questions and checkboxes regarding examination frequency and installation correctness.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with 6 columns: Standard, API RP 4G CAT III & ASTM E709, Viewing Condition, Colored Media, Method, WET. Lists equipment like Yoke, Vernier Caliper, etc.

NDT Results

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect: NONE

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

Table with 2 columns: Name of Inspector, Name of person authenticating this report. Includes signatures and dates.

