



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hilong Oil Services & Engineering	Rig Number:	HL-101	Job Number:	ATS-04-24-3079
---------------------	--	--------------------	---------------	--------------------	-----------------------

Date of Examination:	12-04-2024	Date of Report:	12-04-2024	Certificate No:	ATS-04-24-3079- MPI-06/32
-----------------------------	-------------------	------------------------	-------------------	------------------------	----------------------------------

Pad Eyes S/N:	QTY	Description	SWL	Date of last Thorough examination
P1 P2 P3 P4	04	Fabricated Pad Eyes Pad Eye Dimension Thickness: 26 mm Pin Hole : 49 mm Height: 140 mm Length: 200 mm Location : Sewage Tank No:23206	8 Ton	New

Reference Standard: LEEA DOC 048:2015

Is this the first examination after Installation or assembly at a new site or location?	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>		YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>		YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>		YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

NDT Equipment Details					
Standard	API RP 4G CAT III & ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	AC	Serial No:	201504044	Due Date	04-07-2024
Vernier Caliper	Digital	Serial No:	8914	Due Date	04-07-2024
White Contrast	FLUXO: WCP-4	Batch No:	L230523/1	Due Date	23-05-2028
Black Ink	FLUXO: Black magnetic ink-3	Batch No:	L230125/3	Due Date	25-1-2025

NDT Results

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect: **NONE**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

Name of Inspector:	Name of person authenticating this report:	
Jaafar Badr	Hasan Omran	
	Signature & Stamp:	
Latest date by which next thorough examination must be carried out: 11-10-2024		