



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Rig Number, Job Number, etc. Values include Hilong Oil Services & Engineering, HL100, and ATS-03-24-3078.

Table with 5 columns: Date of Examination, Date of Report, Certificate No. Values include 18/04/2024 and ATS-03-24-3078-MPI-003.

Main equipment details table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes images of pad eyes.

Reference Standard and examination questions table. Reference: LEEA DOC 048:2015. Questions about examination frequency and safety.

Defect identification table. Questions about defects of immediate or potential danger.

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES [checked] NO

NDT Equipment Details table with columns: Standard, Viewing Condition, Colored Media, Method, WET. Lists equipment like Yoke, Vernier Caliper, etc.

NDT Results section. Visual and MPI carried out for the above description and found free of surface defects.

Inspector and authenticator information table. Name of Inspector: Abdullah Mofeed, Name of person authenticating this report: Hasan Omran.

