



# Aberdeen Technical Services and General Transportation

## Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	<b>Hilong Oil Services &amp; Engineering</b>	Certificate Number:	ATS-04-24-3135- MPI-001
Rig Number:	HL99	Job No:	ATS-04-24-3135
Location:	Southern Rumila – RU193	Page No:	01 of 01
Date of Inspection:	22-04-2024	Next Inspection Date:	21-10-2024
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444

**PICTORIAL:**



**Item Description: Caravan Lifting Points**

SN	<b>YF001</b>	<b>YF003</b>
SN	<b>YF002</b>	<b>YF004</b>
SWL	50 KN	

**Unit Serial Number:**  
20231009142

**Details of inspection method(s):**  
Visible magnetic particle inspection

**Inspection Results:**  
MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE ABOVE-MENTIONED ITEMS AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.

**Remarks: ACCEPTED**

Inspection Equipment Details			Personnel Details		Company Stamp
<b>Equipment</b>	Ac yoke		Inspector:	Aram Dlawar	
Serial Number	201504044		Qualifications	ASNT LEVEL II	
Calibration Date:	05-01-2024		Date:	22-04-2024	
Calibration Due:	04-07-2024		Signature:		
<b>Consumables</b>	MAGNETIC PARTICLES INSPECTION		Supervisor:	Hasan Omran	
Maker and Model	FLUXO	FLUXO	Date:	22-04-2024	
Type:	WCP-4	Black magnetic ink-3			
Batch Number	L230523/1	L230125/3			
Expiry Date:	23-05-2028	25-1-2025			

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: [akader@aberdeents.com](mailto:akader@aberdeents.com)  
[inspection@aberdeents-iq.com](mailto:inspection@aberdeents-iq.com)  
 Tel: +964 7833334444 +964 7822222633