




Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	16-04-2024
Location of Examination:	HL 101 – Hilong Base	Date of Certificate:	16-04-2024
Certificate Number:	ATS-04-24-3079-001	Last Examination Date:	-
Job Number:	ATS-04-24-3079	Next Date of Examination:	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H37 H28 H27 H30 H15 H18 H11 H13 H16 H22	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8"</p> <p>GRADE: 6</p> <p>Manufactured: J&L</p> <p>F.O.S: 6:1</p> 	10	6.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**



Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
<p align="center">Hasan Omran</p>  <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	<p align="center">Majd Dayoub</p> 	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF E-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	16-04-2024
Location of Examination:	HL 101 – Hilong Base	Date of Certificate:	16-04-2024
Certificate Number:	ATS-04-24-3079-002	Last Examination Date:	-
Job Number:	ATS-04-24-3079	Next Date of Examination:	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H19 H33 H12 H34 H32 H24 H17 H21 H10 H20	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8"</p> <p>GRADE: 6</p> <p>Manufactured: J&L</p> <p>F.O.S: 6:1</p> 	10	6.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
<p align="center">Hasan Omran</p> <p align="center"><i>(Signature)</i></p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	<p align="center">Majd Dayoub</p> <p align="center"><i>(Signature)</i></p>	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	16-04-2024
Location of Examination:	HL 101 – Hilong Base	Date of Certificate:	16-04-2024
Certificate Number:	ATS-04-24-3079-003	Last Examination Date:	-
Job Number:	ATS-04-24-3079	Next Date of Examination:	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H7 H5 H6 H2 H9 H1	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 7/8"</p> <p>GRADE: 6</p> <p>Manufactured: J&L</p> <p>F.O.S: 6:1</p> 	06	6.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
<p align="center">Hasan Omran</p> <p align="center"><i>(Signature)</i></p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	<p align="center">Majd Dayoub</p> <p align="center"><i>(Signature)</i></p>	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	16-04-2024
Location of Examination:	HL 101 – Hilong Base	Date of Certificate:	16-04-2024
Certificate Number:	ATS-04-24-3079-004	Last Examination Date:	-
Job Number:	ATS-04-24-3079	Next Date of Examination:	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H26 H3 H8 H4	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1” GRADE: 6 Manufactured: J&L F.O.S: 6:1</p>	04	8.5 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center"><i>(Signature)</i></p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center"><i>(Signature)</i></p> <p align="center">Majd Dayoub</p>	Stamp and Date:
--	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	16-04-2024
Location of Examination:	HL 101 – Hilong Base	Date of Certificate:	16-04-2024
Certificate Number:	ATS-04-24-3079-005	Last Examination Date:	-
Job Number:	ATS-04-24-3079	Next Date of Examination:	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H23 H25	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 3/4” GRADE: 6 Manufactured: J&L F.O.S: 6:1</p> 	02	4.75 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature:	Authenticated By:	Stamp and Date:
<p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	<p align="center">Majd Dayoub</p>	

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	16-04-2024
Location of Examination:	HL 101 – Hilong Base	Date of Certificate:	16-04-2024
Certificate Number:	ATS-04-24-3079-006	Last Examination Date:	-
Job Number:	ATS-04-24-3079	Next Date of Examination:	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H29 H35 H36 H37 H38 H39 H40 H41 H42 H43	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1/2"</p> <p>GRADE: 6</p> <p>Manufactured: J&L</p> <p>F.O.S: 6:1</p>	10	2 Ton

Reference Standards BS EN 13889:2003 + A1:2008

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
				After the occurrence of exceptional circumstances?	YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center"><i>(Signature)</i></p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center"><i>(Signature)</i></p> <p align="center">Majd Dayoub</p>	Stamp and Date:
---	---	----------------------------

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF F-002 ISSUE 3 - MAR 2021



Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

Client Name:	HILONG OIL SERVICE AND ENG CO, Iraq	Date of Examination:	16-04-2024
Location of Examination:	HL 101 – Hilong Base	Date of Certificate:	16-04-2024
Certificate Number:	ATS-04-24-3079-007	Last Examination Date:	-
Job Number:	ATS-04-24-3079	Next Date of Examination:	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H44 H45 H46 H47 H48 H49	<p align="center">BOW SHACKLE</p> <p align="center">With HEX, Bolt, Nut, And Safety Cotter Pin:</p> <p>SIZE: 1/2"</p> <p>GRADE: 6</p> <p>Manufactured: J&L</p> <p>F.O.S: 6:1</p> 	06	2 Ton

Reference Standards	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES	√	NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES NO

Inspector Name, Qualifications & signature: <p align="center">Hasan Omran</p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center">LEEA Registered Technician</p>	Authenticated By: <p align="center">Majd Dayoub</p>	Stamp and Date: 
---	--	---

THIS IS TO CERTIFY THAT: a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF F-002 ISSUE 3 - MAR 2021