



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	16-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	16-04-2024
<b>Certificate Number:</b>	ATS-04-24-3079-008	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3079	<b>Next Date of Examination:</b>	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
S2311009DL (1)	<p><b>SINGLE LEG WIRE ROPE SLINGE</b></p> <p>19 mm Diameter, 38.7 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: Guy Line</p>	01	66 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? YES √ NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  <b>ASNT LEVEL II (VT, MT, PT, UT)</b>  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>   <b>Majd Dayoub</b>	<b>Stamp and Date:</b>  <b>ABERDEEN TECHNICAL SERVICES</b> <b>ABERDEEN</b> <b>TECHNICAL SERVICES</b> <b>الخدمات التقنية</b>
--	--	--

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date given above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	16-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	16-04-2024
<b>Certificate Number:</b>	ATS-04-24-3079-009	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3079	<b>Next Date of Examination:</b>	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
TGL202311093004-01 (3) TGL202311093004-02 (4)	<b>SINGLE LEG WIRE ROPE SLINGE</b>  22 mm Diameter, 30.5 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.  FOS: 5:1 Location: Mast Power Swivel	02	4 Ton

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
---	--	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date given above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	16-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	16-04-2024
<b>Certificate Number:</b>	ATS-04-24-3079-010	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3079	<b>Next Date of Examination:</b>	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	MBL
S2311007DL (5) S2311008DL (6)	<b>SINGLE LEG WIRE ROPE SLINGE</b>  22 mm Diameter, 37.6 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.  FOS: 5:1 Location: Guy Line	02	240 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  ASNT LEVEL II (VT, MT, PT, UT)  LEEA Registered Technician	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
--	--	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date given above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	16-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	16-04-2024
<b>Certificate Number:</b>	ATS-04-24-3079-011	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3079	<b>Next Date of Examination:</b>	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
R7	<p><b>SINGLE LEG WIRE ROPE SLINGE</b></p> <p>19 mm Diameter, 34.7 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: Guy Line</p>	01	66 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**


Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? YES √ NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p><b>Hasan Omran</b> ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician</p>	<b>Authenticated By:</b>  <p><b>Majd Dayoub</b></p>	<b>Stamp and Date:</b>  
---	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date given above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	16-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	16-04-2024
<b>Certificate Number:</b>	ATS-04-24-3079-012	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3079	<b>Next Date of Examination:</b>	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
R8	<p><b>SINGLE LEG WIRE ROPE SLINGE</b></p> <p>19 mm Diameter, 17 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: Guy Line</p>	01	66 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES √ NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  <b>ASNT LEVEL II (VT, MT, PT, UT)</b>  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>   <b>Majd Dayoub</b>	<b>Stamp and Date:</b>  <b>ABERDEEN TECHNICAL SERVICES</b> <b>ABERDEEN</b> <b>TECHNICAL SERVICES</b> <b>الخدمات التقنية</b>
--	--	--

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date given above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation  
Iraq –Basra – AlBarjisia  
[Akader@aberdeents.com](mailto:Akader@aberdeents.com) / [inspection@aberdeents-iq.com](mailto:inspection@aberdeents-iq.com)  
Tel: +964 782222633 / +9647827451212



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	16-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	16-04-2024
<b>Certificate Number:</b>	ATS-04-24-3079-013	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3079	<b>Next Date of Examination:</b>	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
9 10	<b>SINGLE LEG WIRE ROPE SLINGE</b>  19 mm Diameter, 58.5 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.  FOS: 5:1 Location: Guy Line	02	66.5 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  <b>ASNT LEVEL II (VT, MT, PT, UT)</b>  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
--	--	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date given above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	16-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	16-04-2024
<b>Certificate Number:</b>	ATS-04-24-3079-014	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3079	<b>Next Date of Examination:</b>	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
11 12 13 14	<b>SINGLE LEG WIRE ROPE SLINGE</b>  19 mm Diameter, 58.5 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.  FOS: 5:1 Location: Guy Line	04	66 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
---	--	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date given above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	16-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	16-04-2024
<b>Certificate Number:</b>	ATS-04-24-3079-015	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3079	<b>Next Date of Examination:</b>	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY24014936	<p><b>SINGLE LEG WIRE ROPE SLINGE</b></p> <p>8 mm Diameter, 34 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: Mast Ladder</p>	01	6 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES √ NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>   <b>Majd Dayoub</b>	<b>Stamp and Date:</b>  ABERDEEN TECHNICAL SERVICES ABERDEEN TECHNICAL SERVICES الخدمت التقنية
---	--	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date given above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation  
Iraq –Basra – AlBarjisia  
[Akader@aberdeents.com](mailto:Akader@aberdeents.com) / [inspection@aberdeents-iq.com](mailto:inspection@aberdeents-iq.com)  
Tel: +964 782222633 / +9647827451212



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	16-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	16-04-2024
<b>Certificate Number:</b>	ATS-04-24-3079-016	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3079	<b>Next Date of Examination:</b>	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY24014937	<p><b>SINGLE LEG WIRE ROPE SLINGE</b></p> <p>14 mm Diameter, 60 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.</p> <p>FOS: 5:1 Location: Mast Escape line</p>	01	18.4 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? YES √ NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  <b>ASNT LEVEL II (VT, MT, PT, UT)</b>  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>   <b>Majd Dayoub</b>	<b>Stamp and Date:</b>  <b>ABERDEEN TECHNICAL SERVICES</b> <b>ABERDEEN</b> <b>TECHNICAL SERVICES</b> <b>الخدمات التقنية</b>
--	--	--

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date given above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



Aberdeen Technical Services and General Transportation  
Iraq –Basra – AlBarjisia  
[Akader@aberdeents.com](mailto:Akader@aberdeents.com) / [inspection@aberdeents-iq.com](mailto:inspection@aberdeents-iq.com)  
Tel: +964 782222633 / +9647827451212



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	16-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	16-04-2024
<b>Certificate Number:</b>	ATS-04-24-3079-017	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3079	<b>Next Date of Examination:</b>	15-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
JB2023110126 JB2023110110 JB2023110111	<b>SINGLE LEG WIRE ROPE SLINGE</b>  14 mm Diameter, 1.2 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Hard Eye.  FOS: 5:1 Location: Attach With Mast Fall Arrestor	03	18 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?								
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
				Within an interval of 12 months?	YES		NO	√	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
---	--	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date given above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021