



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-034	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H 53 H 54 H 55 H 56	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1 1/4” <b>GRADE:</b> 6 <b>Manufactured:</b> DY <b>F.O.S:</b> 6:1</p>	04	12 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  Hasan Omran <i>(Signature)</i> ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	<b>Authenticated By:</b>  <i>(Signature)</i> Majd Dayoub	<b>Stamp and Date:</b> 
---	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-035	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H 57 B 01 10	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1 1/4” <b>GRADE:</b> 6 <b>Manufactured:</b> HK <b>F.O.S:</b> 6:1</p> 	03	12 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons  YES  NO

Is the above a defect which is not yet but could become a danger to persons  YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose?  YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>	<b>Authenticated By:</b>	<b>Stamp and Date:</b>
<p align="center"><b>Hasan Omran</b></p> <p align="center"><b>ASNT LEVEL II (VT, MT, PT, UT)</b></p> <p align="center"><b>LEEA Registered Technician</b></p>	<p align="center"><b>Majd Dayoub</b></p>	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-036	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
HL 0011 HL 0012	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 1 1/4” <b>GRADE:</b> 6 <b>Manufactured:</b> Crosby <b>F.O.S:</b> 6:1</p>	02	12 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
*Items mentioned-above was inspected Visually and Dimensionally at the time of inspection*

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center"><b>Hasan Omran</b></p> <p align="center"><i>ASNT LEVEL II (VT, MT, PT, UT)</i></p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p align="center"><i>Majd Dayoub</i></p>	<b>Stamp and Date:</b> 
--	--	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



**Certificate of Test and Thorough Examination of Lifting Equipment**

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-037	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H 58 H 59 H 60 H 61 H 62	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 1”</b> <b>GRADE: 6</b> <b>Manufactured: J &amp; L</b> <b>F.O.S: 6:1</b></p>	05	8.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons  YES  NO

Is the above a defect which is not yet but could become a danger to persons  YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose?  YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  Hasan Omran <i>(Signature)</i> ASNT LEVEL II (VT, MT, PT, UT) LEEA Registered Technician	<b>Authenticated By:</b>  Majd Dayoub <i>(Signature)</i>	<b>Stamp and Date:</b> 
---	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-038	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H 63 H 64 H 65 H 66 H 104 H 105	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 1”</b> <b>GRADE: 6</b> <b>Manufactured: DY</b> <b>F.O.S: 6:1</b></p> 	06	8.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?				Was the examination carried out?					
	YES		NO		Within an interval of 12 months?	YES		NO	√
				Was the examination carried out?					
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?				
					YES		NO	√	

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons  YES  NO

Is the above a defect which is not yet but could become a danger to persons  YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose?  YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>	<b>Authenticated By:</b>	<b>Stamp and Date:</b>
<p align="center"><b>Hasan Omran</b></p> <p align="center"><i>(Signature)</i></p> <p align="center"><b>ASNT LEVEL II (VT, MT, PT, UT)</b></p> <p align="center"><b>LEEA Registered Technician</b></p>	<p align="center"><b>Majd Dayoub</b></p> <p align="center"><i>(Signature)</i></p>	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-039	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
XX2200578	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 1”</b>  <b>GRADE: 6</b>  <b>Manufactured: HX</b>  <b>F.O.S: 6:1</b></p> 	01	8.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons  YES  NO

Is the above a defect which is not yet but could become a danger to persons  YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose?  YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>	<b>Authenticated By:</b>	<b>Stamp and Date:</b>
<p align="center"><b>Hasan Omran</b></p> <p align="center"><b>ASNT LEVEL II (VT, MT, PT, UT)</b></p> <p align="center"><b>LEEA Registered Technician</b></p>	<p align="center"><b>Majd Dayoub</b></p>	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-040	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H 67 H 68 H 69 H 70 H 126	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 7/8"</b></p> <p><b>GRADE: 6</b></p> <p><b>Manufactured: J &amp; L</b></p> <p><b>F.O.S: 6:1</b></p> 	05	6.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons  YES  NO

Is the above a defect which is not yet but could become a danger to persons  YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose?  YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>	<b>Authenticated By:</b>	<b>Stamp and Date:</b>
<p align="center"><b>Hasan Omran</b></p>  <p align="center"><b>ASNT LEVEL II (VT, MT, PT, UT)</b></p> <p align="center"><b>LEEA Registered Technician</b></p>	<p align="center"><b>Majd Dayoub</b></p> 	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-041	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H 71 H 72 H 73	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 7/8” <b>GRADE:</b> 6 <b>Manufactured:</b> DY <b>F.O.S:</b> 6:1</p> 	03	6.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons  YES  NO

Is the above a defect which is not yet but could become a danger to persons  YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose?  YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>	<b>Authenticated By:</b>	<b>Stamp and Date:</b>
<p align="center"><b>Hasan Omran</b></p> <p align="center"><b>ASNT LEVEL II (VT, MT, PT, UT)</b></p> <p align="center"><b>LEEA Registered Technician</b></p>	<p align="center"><b>Majd Dayoub</b></p>	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-042	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B 9975 B 9977 B 9978 B 9979 B 9980	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 7/8”</p> <p><b>GRADE:</b> 6</p> <p><b>Manufactured:</b> Toyolift</p> <p><b>F.O.S:</b> 6:1</p> 	05	6.5 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>	<b>Authenticated By:</b>	<b>Stamp and Date:</b>
<p align="center"><b>Hasan Omran</b></p>  <p align="center"><b>ASNT LEVEL II (VT, MT, PT, UT)</b></p> <p align="center"><b>LEEA Registered Technician</b></p>	<p align="center"><b>Majd Dayoub</b></p> 	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-043	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H 74 H 75 H 76 H 77 H 78 H 79 H 80	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 3/4"</b></p> <p><b>GRADE: 6</b></p> <p><b>Manufactured: J &amp; L</b></p> <p><b>F.O.S: 6:1</b></p> 	07	4.75 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?				Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO
				After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons  YES  NO

Is the above a defect which is not yet but could become a danger to persons  YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose?  YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>	<b>Authenticated By:</b>	<b>Stamp and Date:</b>
<p align="center"><b>Hasan Omran</b></p>  <p align="center"><b>ASNT LEVEL II (VT, MT, PT, UT)</b></p> <p align="center"><b>LEEA Registered Technician</b></p>	<p align="center"><b>Majd Dayoub</b></p> 	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-044	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H 81 H 82 H 83 H 84 H 85 H 86 H 87	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 3/4"</b></p> <p><b>GRADE: 6</b></p> <p><b>Manufactured: J &amp; L</b></p> <p><b>F.O.S: 6:1</b></p> 	07	4.75 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons  YES  NO

Is the above a defect which is not yet but could become a danger to persons  YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose?  YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>	<b>Authenticated By:</b>	<b>Stamp and Date:</b>
<p align="center"><b>Hasan Omran</b></p> <p align="center"><i>(Signature)</i></p> <p align="center"><b>ASNT LEVEL II (VT, MT, PT, UT)</b></p> <p align="center"><b>LEEA Registered Technician</b></p>	<p align="center"><b>Majd Dayoub</b></p> <p align="center"><i>(Signature)</i></p>	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-045	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H 88 H 89	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE:</b> 3/4” <b>GRADE:</b> 6 <b>Manufactured:</b> DY <b>F.O.S:</b> 6:1</p> 	02	4.75 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons  YES  NO

Is the above a defect which is not yet but could become a danger to persons  YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose?  YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>	<b>Authenticated By:</b>	<b>Stamp and Date:</b>
<p align="center"><b>Hasan Omran</b></p> <p align="center"><b>ASNT LEVEL II (VT, MT, PT, UT)</b></p> <p align="center"><b>LEEA Registered Technician</b></p>	<p align="center"><b>Majd Dayoub</b></p>	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-046	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H 90 H 91 H 92 H 93 H 94 H 95 H 96 H 97	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 5/8"</b></p> <p><b>GRADE: 6</b></p> <p><b>Manufactured: J &amp; L</b></p> <p><b>F.O.S: 6:1</b></p> 	08	3.25 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons  YES  NO

Is the above a defect which is not yet but could become a danger to persons  YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose?  YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>	<b>Authenticated By:</b>	<b>Stamp and Date:</b>
<p align="center"><b>Hasan Omran</b></p>  <p align="center"><b>ASNT LEVEL II (VT, MT, PT, UT)</b></p> <p align="center"><b>LEEA Registered Technician</b></p>	<p align="center"><b>Majd Dayoub</b></p> 	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-047	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H 98 H 99	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 5/8"</b> <b>GRADE: 6</b> <b>Manufactured: DY</b> <b>F.O.S: 6:1</b></p> 	02	3.25 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?				Was the examination carried out?					
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons  YES  NO

Is the above a defect which is not yet but could become a danger to persons  YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose?  YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>	<b>Authenticated By:</b>	<b>Stamp and Date:</b>
<p align="center"><b>Hasan Omran</b></p> <p align="center"><b>ASNT LEVEL II (VT, MT, PT, UT)</b></p> <p align="center"><b>LEEA Registered Technician</b></p>	<p align="center"><b>Majd Dayoub</b></p>	

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-048	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H 100 H 101	<p align="center"><b>BOW SHACKLE</b></p> <p align="center"><b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b></p> <p><b>SIZE: 1/2"</b> <b>GRADE: 6</b> <b>Manufactured: J &amp; L</b> <b>F.O.S: 6:1</b></p> 	02	2 Ton

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center"><b>Hasan Omran</b></p> <p align="center"><b>ASNT LEVEL II (VT, MT, PT, UT)</b></p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p align="center"><b>Majd Dayoub</b></p>	<b>Stamp and Date:</b>  
--	--	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.


ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	HILONG OIL SERVICE AND ENG CO, Iraq	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-049	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H 102 H 103	<b>BOW SHACKLE</b> <b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b>  <b>SIZE: 1/2"</b> <b>GRADE: 6</b> <b>Manufactured: DY</b> <b>F.O.S: 6:1</b>	02	2 Ton
			

<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?					Was the examination carried out?				
	YES		NO	√	Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**


Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p style="text-align: center;"><b>Hasan Omran</b></p> <p style="text-align: center;">ASNT LEVEL II (VT, MT, PT, UT)</p> <p style="text-align: center;"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p style="text-align: center;"><b>Majd Dayoub</b></p>	<b>Stamp and Date:</b>  
--	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021




## Certificate of Test and Thorough Examination of Lifting Equipment

*This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307*

<b>Client Name:</b>	HILONG OIL SERVICE AND ENG CO, Iraq	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-050	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
H 51 H 52 H 104 H 105 H 106 H 107 H 108 H 109 H 110 H 111 H 112 H 113	<b>BOW SHACKLE</b>  <b>With HEX, Bolt, Nut, And Safety Cotter Pin:</b>  <b>SIZE: 1 3/8"</b> <b>GRADE: 6</b> <b>Manufactured: J &amp; L</b> <b>F.O.S: 6:1</b>	12	13.5 Ton



<b>Reference Standards</b>	BS EN 13889:2003 + A1:2008
----------------------------	----------------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **none**

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: visual inspection:  
Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? YES  √  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p style="text-align: center;"><b>Hasan Omran</b></p> <p style="text-align: center;">ASNT LEVEL II (VT, MT, PT, UT)</p> <p style="text-align: center;"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p style="text-align: center;"><b>Majd Dayoub</b></p>	<b>Stamp and Date:</b>  
--	---	--------------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

**ATS-LIF-F-002 ISSUE 3 - MAR 2021**