



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-018	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
CS23122837 CS23122838	<b>4-LEG WIRE ROPE SLINGE</b>  32 mm Diameter, 6 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, WITH MASTER LINK ASSEMBLY Hard Eye AT Both Ends.  FOS: 5:1 Location: Rig Store	02	19.4 Ton

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  <b>ASNT LEVEL II (VT, MT, PT, UT)</b>  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
--	--	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above, and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-019	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
CS23122827 CS23122828 CS23122830	<b>4-LEG WIRE ROPE SLINGE</b>  22 mm Diameter, 8 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, WITH MASTER LINK ASSEMBLY Hard Eye X Soft Eye.  FOS: 5:1 Location: Rig Store	03	9 Ton

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  Hasan Omran  ASNT LEVEL II (VT, MT, PT, UT)  LEEA Registered Technician	<b>Authenticated By:</b>  Majd Dayoub	<b>Stamp and Date:</b> 
---	---	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above, and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-020	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
CS23122831 CS23122832	<b>4-LEG WIRE ROPE SLINGE</b>  26 mm Diameter, 8 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, WITH MASTER LINK ASSEMBLY Hard Eye AT Both Ends,  FOS: 5:1 Location: Rig Store	02	12.8 Ton

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  <b>ASNT LEVEL II (VT, MT, PT, UT)</b>  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
--	--	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above, and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-021	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
CS23122833 CS23122834 CS23122836	<p align="center"><b>4-LEG WIRE ROPE SLINGE</b></p> <p>36 mm Diameter, 6 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, WITH MASTER LINK ASSEMBLY Hard Eye AT Both Ends,  FOS: 5:1 Location: Rig Store</p>	03	24.6 Ton

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?	YES	√	NO	
					Within an interval of 6 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center"><b>Hasan Omran</b></p> <p align="center"><b>ASNT LEVEL II (VT, MT, PT, UT)</b></p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p align="center"><b>Majd Dayoub</b></p>	<b>Stamp and Date:</b>  
--	--	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021





## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-022	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
B 9582	<p><b>4-LEG WIRE ROPE SLINGE</b></p> <p>16 mm Diameter, 1.5 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, WITH MASTER LINK ASSEMBLY Hard Eye X Soft Eye,  FOS: 5:1 Location: Rig Store</p>	01	6.9 Ton

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	Was the examination carried out?			
	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO	In accordance with an examination scheme? YES √ NO After the occurrence of exceptional circumstances? YES NO √

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? YES √ NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <p style="text-align: center;"><b>Hasan Omran</b></p> <p style="text-align: center;">ASNT LEVEL II (VT, MT, PT, UT)</p> <p style="text-align: center;"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p style="text-align: center;"><b>Majd Dayoub</b></p>	<b>Stamp and Date:</b>  
--	---	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-023	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
CS23122835	<p align="center"><b>TWO LEG WIRE ROPE SLINGE</b></p> <p>36 mm Diameter, 6 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, WITH MASTER LINK Hard Eye At Both Ends,  FOS: 5:1 Location: Rig Store</p>	01	24.6 Ton

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  <b>ASNT LEVEL II (VT, MT, PT, UT)</b>  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
--	--	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above, and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-024	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY23126048 GY23126051 GY23126052 GY23126053	<b>SINGLE LEG WIRE ROPE SLINGE</b>  26 mm Diameter, 8 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, Soft Eye At Both Ends,  FOS: 5:1 Location: Rig Store	04	63.5 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  <b>ASNT LEVEL II (VT, MT, PT, UT)</b>  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
--	--	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above, and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-025	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY23126062 GY23126063 GY23126064 GY23126065 GY23126066 GY23126067 GY23126068 GY23126069	<b>SINGLE LEG WIRE ROPE SLINGE</b>  19 mm Diameter, 4 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, Soft Eye At Both Ends,  FOS: 5:1 Location: Rig Store	08	33.9 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES** by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above was inspected **Visually and Dimensionally** at the time of inspection

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>   <b>Majd Dayoub</b>	<b>Stamp and Date:</b>  
---	--	--------------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-026	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY23126034 GY23126035 GY23126036 GY23126037 GY23126038 GY23126039 GY23126040 GY23126041 GY23126042 GY23126043 GY23126044 GY23126045	<b>SINGLE LEG WIRE ROPE SLINGE</b>  36 mm Diameter, 6 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, Soft Eye At Both Ends,  FOS: 5:1 Location: Rig Store	12	121.9 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?					
					Within an interval of 6 months?		YES	√	NO	
					Within an interval of 12 months?		YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?		YES	√	NO	
					After the occurrence of exceptional circumstances?		YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons YES  NO

Is the above a defect which is not yet but could become a danger to persons YES by

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? YES  NO

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  <b>ASNT LEVEL II (VT, MT, PT, UT)</b>  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
--	--	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-027	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY23126046 GY23126047 GY23126048 GY23126050	<b>SINGLE LEG WIRE ROPE SLINGE</b>  26 mm Diameter, 8 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, Soft Eye At Both Ends,  FOS: 5:1 Location: Rig Store	04	63.5 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  <b>ASNT LEVEL II (VT, MT, PT, UT)</b>  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
--	--	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above, and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-028	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY23126054 GY23126055 GY23126056 GY23126057 GY23126058 GY23126059 GY23126060	<b>SINGLE LEG WIRE ROPE SLINGE</b>  19 mm Diameter, 2 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, Soft Eye At Both Ends,  FOS: 5:1 Location: Rig Store	07	33.9 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?					Within an interval of 12 months?	YES		NO	√
	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
---	--	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above, and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-029	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY23126070 GY23126071 GY23126072 GY23126073 GY23126074 GY23126075 GY23126076 GY23126077 GY23126078 GY23126079	<b>SINGLE LEG WIRE ROPE SLINGE</b>  19 mm Diameter, 1 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, Hard Eye At Both Ends,  FOS: 5:1 Location: Rig Store	10	33.9 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:

Items mentioned-above was inspected Visually and Dimensionally at the time of inspection

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  ASNT LEVEL II (VT, MT, PT, UT)  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b>  
---	--	--------------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above, and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-030	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY23126080 GY23126081 GY23126082 GY23126083 GY23126084 GY23126086 GY23126087 GY23126088	<b>SINGLE LEG WIRE ROPE SLINGE</b>  19 mm Diameter, 0.8 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, Hard Eye At Both Ends,  FOS: 5:1 Location: Rig Store	08	33.9 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  <b>ASNT LEVEL II (VT, MT, PT, UT)</b>  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
--	--	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above, and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-031	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
GY23126080 GY23126085	<b>SINGLE LEG WIRE ROPE SLINGE</b>  19 mm Diameter, 8 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, Hard Eye At Both Ends,  FOS: 5:1 Location: Rig Store	02	33.9 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		Within an interval of 12 months?	YES		NO	√
					In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  <b>ASNT LEVEL II (VT, MT, PT, UT)</b>  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
--	--	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above, and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-032	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
JB2023110126 JB2023110107 JB2023110111	<b>SINGLE LEG WIRE ROPE SLINGE</b>  14 mm Diameter, 1.2 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, Hard Eye At Both Ends,  FOS: 5:1 Location: Rig Store	03	18 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <b>Hasan Omran</b>  <b>ASNT LEVEL II (VT, MT, PT, UT)</b>  <b>LEEA Registered Technician</b>	<b>Authenticated By:</b>  <b>Majd Dayoub</b>	<b>Stamp and Date:</b> 
--	--	----------------------------

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above, and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021



# Aberdeen Technical Services and General Transportation



## Certificate of Test and Thorough Examination of Lifting Equipment

This Report Complies with The Requirements of The Lifting Operations and Lifting Equipment Regulations 1998 S.I. No. 2307

<b>Client Name:</b>	<b>HILONG OIL SERVICE AND ENG CO, Iraq</b>	<b>Date of Examination:</b>	21-04-2024
<b>Location of Examination:</b>	HL 101 – Hilong Base	<b>Date of Certificate:</b>	21-04-2024
<b>Certificate Number:</b>	ATS-04-24-3089-033	<b>Last Examination Date:</b>	-
<b>Job Number:</b>	ATS-04-24-3089	<b>Next Date of Examination:</b>	20-10-2024

Serial No: / Asset No:	Description of The Equipment	Qty:	SWL
JB2023100144	<p align="center"><b>SINGLE LEG WIRE ROPE SLINGE</b></p> <p>10 mm Diameter, 1.2 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE, Hard Eye At Both Ends,  FOS: 5:1 Location: Rig Store</p>	01	18 KN

<b>Reference Standards</b>	BS EN 13414-1+A2:2008
----------------------------	-----------------------

Is this the first examination after installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out?				
					Within an interval of 6 months?	YES	√	NO	
					Within an interval of 12 months?	YES		NO	√
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		In accordance with an examination scheme?	YES	√	NO	
					After the occurrence of exceptional circumstances?	YES		NO	√

Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: **None**

Is the above a defect which is of immediate danger to persons **YES**  **NO**

Is the above a defect which is not yet but could become a danger to persons **YES by**

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **None**

Particulars of any tests carried out as part of the examination:  
  
**Items mentioned-above was inspected Visually and Dimensionally at the time of inspection**

Is this Equipment Fit for Purpose? **YES**  **NO**

<b>Inspector Name, Qualifications &amp; signature:</b>  <p align="center"><b>Hasan Omran</b></p> <p align="center">ASNT LEVEL II (VT, MT, PT, UT)</p> <p align="center"><b>LEEA Registered Technician</b></p>	<b>Authenticated By:</b>  <p align="center"><b>Majd Dayoub</b></p>	<b>Stamp and Date:</b>  
---	--	---

**THIS IS TO CERTIFY THAT:** a competent person did attend the above-mentioned owner's work location on the date shown above, and the equipment described in this report has been Thoroughly Examined as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found **Satisfactory** at the time of Inspection and considered **Safe** for Lifting.

ATS-LIF-F-002 ISSUE 3 - MAR 2021