



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Rig Number, Job Number, etc.

Table with 6 columns: Date of Examination, Date of Report, Certificate No, etc.

Main table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes images of pad eyes.

Reference Standard table with columns for examination questions and answers.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A


Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with columns: Standard, Viewing Condition, Colored Media, Method, WET, etc.

NDT Results section: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection. Identification of any part found to have a defect and a description of the defect: NONE. Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

Table with columns: Name of Inspector, Name of person authenticating this report, Latest date by which next thorough examination must be carried out: 11-11-2024





Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Rig Number, Job Number, etc.

Table with 6 columns: Date of Examination, Date of Report, Certificate No, etc.

Main table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes images of pad eyes.

Reference Standard table with columns for examination questions and answers.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with columns: Standard, Viewing Condition, Colored Media, Method, WET. Includes Yoke, Vernier Caliper, White Contrast, Black Ink.

NDT Results section: Visual and MPI carried out for the above description and found free of surface defects at the time of inspection. Identification of any part found to have a defect and a description of the defect: NONE. Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

Table with columns: Name of Inspector, Name of person authenticating this report, Latest date by which next thorough examination must be carried out: 11-11-2024

