



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hilong Oil Services & Engineering	Rig Number:	HL199	Job Number:	ATS-05-24-3200
--------------	-----------------------------------	-------------	-------	-------------	----------------

Date of Examination:	15/05/2024	Date of Report:	15/05/2024	Certificate No:	ATS-05-24-3200-081
----------------------	------------	-----------------	------------	-----------------	--------------------

Serial Number:	QTY	Description	SWL	Date of last Thorough examination
A B C D	04	Fabricated Pad Eyes Pad Eyes Dimension Thickness: 9.81 MM Pin Hole : 37 MM Length : 87 MM Height : 91 MM Location: BELL NIPPLE SN: BL06	1 TON	N/A
				

Reference Standard:		LEEA DOC 048:2015											
Is this the first examination after Installation or assembly at a new site or location?						Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?							
		YES		NO	✓					YES	✓	NO	
If the answer to the above question is YES has the equipment been installed correctly?										YES		NO	✓
		YES		NO						YES	✓	NO	
										YES		NO	✓
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE													
Is the above a defect which is of immediate danger to persons:										YES		NO	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)								N/A					
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE													
IS THIS EQUIPMENT SAFE TO OPERATE?										YES	✓	NO	

NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	AC	Serial No:	201504044	Due Date	04-07-2024
Vernier Caliper	Digital	Serial No:	8914	Due Date	04-07-2024
White Contrast	FLUXO: WCP-4	Batch No:	L230523/1	Due Date	23-05-2028
Black Ink	FLUXO: Black magnetic ink-3	Batch No:	L230125/3	Due Date	25-1-2025

NDT Results	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect: NONE	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE	

Name of Inspector:	Name of person authenticating this report:
Aram Dlawar	Hasan Omran
	Signature & Stamp:
Latest date by which next thorough examination must be carried out: 14-11-2024	

