



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hilong Oil Services & Engineering	Rig Number:	HL199	Job Number:	ATS-05-24-3200
--------------	-----------------------------------	-------------	-------	-------------	----------------

Date of Examination:	15/05/2024	Date of Report:	15/05/2024	Certificate No:	ATS-05-24-3200-087
----------------------	------------	-----------------	------------	-----------------	--------------------

Serial Number:	QTY	Description	SWL	Date of last Thorough examination
DZ063 DZ064	02	Fabricated Pad Eyes Pad Eye Dimension Thickness: 15 MM Pin Hole : 30 MM Length : 99 MM Height : 116 MM Location: BOP TROLEY BEAM SN: B-2	1 TON 	N/A 

Reference Standard:		LEEA DOC 048:2015									
Is this the first examination after Installation or assembly at a new site or location?					Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?						
	YES		NO	✓		YES	✓	NO			
						YES		NO	✓		
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO			YES	✓	NO			
						YES		NO	✓		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE											
Is the above a defect which is of immediate danger to persons:						YES		NO			
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						N/A					
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE											
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	✓	NO			

NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	AC	Serial No:	201504044	Due Date	04-07-2024
Vernier Caliper	Digital	Serial No:	8914	Due Date	04-07-2024
White Contrast	FLUXO: WCP-4	Batch No:	L230523/1	Due Date	23-05-2028
Black Ink	FLUXO: Black magnetic ink-3	Batch No:	L230125/3	Due Date	25-1-2025

NDT Results	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect: NONE	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE	

Name of Inspector:	Name of person authenticating this report:
Aram Dlawar 	Hasan Omran
	Signature & Stamp:
Latest date by which next thorough examination must be carried out: 14-11-2024	

