



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Table with 6 columns: Client Name, Hilong Oil Services & Engineering, Rig Number, HL99, Job Number, ATS-05-24-3200

Table with 6 columns: Date of Examination, 16/05/2024, Date of Report, 16/05/2024, Certificate No, ATS-05-24-3200-110

Main table with columns: Serial Number, QTY, Description, SWL, Date of last Thorough examination. Includes details for Fabricated Pad Eyes and four photographs.

Reference Standard: LEEA DOC 048:2015. Inspection questions and results table.

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

Table with 6 columns: Standard, ASTM E709, Viewing Condition, Colored Media, Method, WET. Includes Yoke, Vernier Caliper, White Contrast, Black Ink.

NDT Results. Visual and MPI carried out for the above description and found free of surface defects at the time of inspection. Identification of any part found to have a defect and a description of the defect: NONE. Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE

Table with 2 columns: Name of Inspector, Name of person authenticating this report. Includes signatures of Aram Dlawar and Hasan Omran.

