



Certificate of Thorough Examination & NDT of Lifting Equipment

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hilong Oil Services & Engineering	Rig Number:	HL-99	Job Number:	ATS-05-24-3200
---------------------	--	--------------------	--------------	--------------------	-----------------------

Date of Examination:	20/05/2024	Date of Report:	20/05/2024	Certificate No:	ATS-05-24-3200-119
-----------------------------	-------------------	------------------------	-------------------	------------------------	---------------------------

Serial Number:	QTY	Description	SWL	Date of last Thorough examination
DZ020 DZ021 DZ022	03	Fabricated Pad Eyes Pad Eye Dimension Thickness: 20 MM Pin Hole : 40 MM Length : 116 MM Height : 114 MM Location: SUPPORTING BEAM SN: B-2	1 TONS	N/A

Reference Standard:	LEEA DOC 048:2015		
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓
Was the examination carried out: Within an interval of 6 months?	YES	NO	✓
With an interval of 12 months?	YES	NO	✓
In accordance with an examination scheme?	YES	NO	✓
After the occurrence of exceptional circumstances?	YES	NO	✓

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES NO

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above: **NONE**

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	AC	Serial No:	201504044	Due Date	04-07-2024
Vernier Caliper	Digital	Serial No:	8914	Due Date	04-07-2024
White Contrast	FLUXO: WCP-4	Batch No:	L230523/1	Due Date	23-05-2028
Black Ink	FLUXO: Black magnetic ink-3	Batch No:	L230125/3	Due Date	25-1-2025

NDT Results	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect: NONE	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: NONE	

Name of Inspector:	Name of person authenticating this report:
Aram Dlawar	Hasan Omran
	Signature & Stamp:
Latest date by which next thorough examination must be carried out: 19-11-2024	

