



Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-05-24-3200- MPI-015									
Rig Number:	HL99	Job No:	ATS-05-24-3200									
Location:	Southern Rumila – RU-149	Page No:	01 of 01									
Date of Inspection:	09-05-2024	Next Inspection Date:	08-11-2024									
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444									
PICTORIAL:		Item Description: CAMP BUNKER										
    		<table border="1"> <tr> <td>SN</td> <td>1</td> <td>3</td> </tr> <tr> <td>SN</td> <td>2</td> <td>4</td> </tr> <tr> <td>SWL</td> <td colspan="2">10 TONS</td> </tr> </table>		SN	1	3	SN	2	4	SWL	10 TONS	
		SN	1	3								
		SN	2	4								
		SWL	10 TONS									
Unit Serial Number: BS99-1												
Details of inspection method(s): Visible magnetic particle inspection												
Inspection Results: MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF LIFTING POINTS OF THE ABOVE-MENTIONED ITEM AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.												
Remarks: ACCEPTED												
Inspection Equipment Details		Personnel Details										
Equipment	Ac yoke	Inspector:	Aram Dlawar									
Serial Number	201504044	Qualifications	ASNT LEVEL II									
Calibration Date:	05-01-2024	Date:	09-05-2024									
Calibration Due:	04-07-2024	Signature:										
Consumables	MAGNETIC PARTICLES INSPECTION		Supervisor:									
Maker and Model	FLUXO	FLUXO	Hasan Omran									
Type:	WCP-4	Black magnetic ink-3	Date:									
Batch Number	L230523/1	L230125/3	10-05-2024									
Expiry Date:	23-05-2028	25-1-2025										
												

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com

Tel: +964 7833334444 +964 7822222633