



Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-05-24-3200- MPI-037
Rig Number:	HL99	Job No:	ATS-05-24-3200
Location:	Southern Rumila – RU-149	Page No:	01 of 01
Date of Inspection:	11-05-2024	Next Inspection Date:	10-11-2024
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444

PICTORIAL:



Item Description:
CONTAINER STORE – Bottom ISO Corner fittings

Unit Serial Number:
GCSU2008070

Details of inspection method(s):
Visible magnetic particle inspection

Inspection Results:
MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE ABOVE-MENTIONED ITEMS AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.

Remarks: **ACCEPTED**

Inspection Equipment Details			Personnel Details		Company Stamp
Equipment	Ac yoke		Inspector:	Aram Dlawar	
Serial Number	201504044		Qualifications	ASNT LEVEL II	
Calibration Date:	05-01-2024		Date:	11-05-2024	
Calibration Due:	04-07-2024		Signature:		
Consumables	MAGNETIC PARTICLES INSPECTION		Supervisor:	Hasan Omran	
Maker and Model	FLUXO	FLUXO	Date:	12-05-2024	
Type:	WCP-4	Black magnetic ink-3			
Batch Number	L230523/1	L230125/3			
Expiry Date:	23-05-2028	25-1-2025			

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com

Tel: +964 7833334444 +964 7822222633