



# Aberdeen Technical Services and General Transportation

## Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	<b>Hilong Oil Services &amp; Engineering</b>	Certificate Number:	ATS-05-24-3200- MPI-040
Rig Number:	HL99	Job No:	ATS-05-24-3200
Location:	Southern Rumila – RU-149	Page No:	01 of 01
Date of Inspection:	11-05-2024	Next Inspection Date:	10-11-2024
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444
<b>PICTORIAL:</b>			<b>Item Description:</b>
			COINTAINER STORE - Bottom ISO Corner Fittings
			<b>Unit Serial Number:</b>
			GESU3064195
			<b>Details of inspection method(s):</b>
Visible magnetic particle inspection	<b>Inspection Results:</b>		
MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE ABOVE-MENTIONED ITEMS AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.	<b>Remarks: ACCEPTED</b>		
<b>Inspection Equipment Details</b>		<b>Personnel Details</b>	
<b>Equipment</b>	Ac yoke		Inspector:
Serial Number	201504044		Qualifications
Calibration Date:	05-01-2024		Date:
Calibration Due:	04-07-2024		Signature:
<b>Consumables</b>	MAGNETIC PARTICLES INSPECTION		Supervisor:
Maker and Model	FLUXO	FLUXO	Hasan Omran
Type:	WCP-4	Black magnetic ink-3	Date:
Batch Number	L230523/1	L230125/3	12-05-2024
Expiry Date:	23-05-2028	25-1-2025	
			<b>Company Stamp</b>

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: [akader@aberdeents.com](mailto:akader@aberdeents.com)  
[inspection@aberdeents-iq.com](mailto:inspection@aberdeents-iq.com)

Tel: +964 7833334444 +964 7822222633