




Aberdeen Technical Services and General Transportation

Certificate of Visual Thorough Examination and Magnetic Particle Inspection (MPI)



Client:	Hilong Oil Services & Engineering	Certificate Number:	ATS-05-24-3200- MPI-041		
Rig Number:	HL99	Job No:	ATS-05-24-3200		
Location:	Southern Rumila – RU-149	Page No:	01 of 01		
Date of Inspection:	11-05-2024	Next Inspection Date:	10-11-2024		
Type of Inspection	Visual inspection & MPI (Wet Visible Method)	Ref. Standards:	ASTM E709, ASTM E 1444		
PICTORIAL:		Item Description:			
		COINTAINER STORE - Bottom ISO Corner Fittings			
		Unit Serial Number: GESU3185047			
		Details of inspection method(s): Visible magnetic particle inspection			
		Inspection Results: MPI WAS CARRIED OUT ON THE CRITICAL AND WELDING AREAS OF THE ABOVE-MENTIONED ITEMS AND FOUND NO CRACKS OR RELEVANT INDICATIONS AT THE TIME OF INSPECTION.			
		Remarks: ACCEPTED			
Inspection Equipment Details		Personnel Details		Company Stamp 	
Equipment	Ac yoke		Inspector:		Aram Dlawar
Serial Number	201504044		Qualifications		ASNT LEVEL II
Calibration Date:	05-01-2024		Date:		11-05-2024
Calibration Due:	04-07-2024		Signature:		
Consumables	MAGNETIC PARTICLES INSPECTION		Supervisor:		Hasan Omran
Maker and Model	FLUXO	FLUXO	Date:		12-05-2024
Type:	WCP-4	Black magnetic ink-3			
Batch Number	L230523/1	L230125/3			
Expiry Date:	23-05-2028	25-1-2025			

ATS-NDT-F-001 ISSUE 3 JUN 2023



E: akader@aberdeents.com
inspection@aberdeents-iq.com

Tel: +964 7833334444 +964 7822222633